

AD-A073 611

SCHNABEL ENGINEERING ASSOCIATES RICHMOND VA
NATIONAL DAM SAFETY PROGRAM. UPPER NORTH RIVER NUMBER 76 (ELKH0--ETC(U)
MAR 79

F/G 13/2

DACW65-79-D-0004

NL

UNCLASSIFIED

1 OF 1

AD
A073611



END
DATE
FILMED

10-19

DDC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

MARCH 1979

Name Of Dam: UPPER NORTH RIVER NO. 76 (ELKHORN LAKE)

Location: AUGUSTA COUNTY, VIRGINIA



Inventory Number: VA. NO. 01506

LEVEL

PHASE I INSPECTION REPORT

NATIONAL DAM SAFETY PROGRAM

AD A 073611



~~DA 073611~~

PREPARED FOR

NORFOLK DISTRICT CORPS OF ENGINEERS
803 FRONT STREET
NORFOLK, VIRGINIA 23510

BY

SCHNABEL ENGINEERING ASSOCIATES, P.C./
J. K. TIMMONS AND ASSOCIATES, INC.

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

DDC FILE COPY

79 09 10 126

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER VA 01506	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Upper North River No. 76 Augusta County, Virginia		5. TYPE OF REPORT & PERIOD COVERED Final
7. AUTHOR(s) Schnabel Engineering Associates, P.C. J. K. Timmons and Associates, Inc.		6. CONTRACT OR GRANT NUMBER(s) Schnabel - DACW 65-79-D-0004
9. PERFORMING ORGANIZATION NAME AND ADDRESS (12) 84 P.		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS U. S. Army Engineering District, Norfolk 803 Front Street Norfolk, VA 23510		12. REPORT DATE March 1979
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) (15) DACW 65-79-D-0004		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. (9) Final rept.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) (6) National Dam Safety Program, Upper North River Number 76 (Elkhorn Lake) (ID Number VA-01506), Augusta County, Virginia, Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams - VA National Dam Safety Program Phase I Dam Safety Dam Inspection		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) (See reverse side)		

20. Abstract

Pursuant to Public Law 92-367, Phase I Inspection Reports are prepared under guidance contained in the recommended guidelines for safety inspection of dams, published by the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general conditions of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

Based upon the field conditions at the time of the field inspection and all available engineering data, the Phase I report addresses the hydraulic, hydrologic, geologic, geotechnic, and structural aspects of the dam. The engineering techniques employed give a reasonably accurate assessment of the conditions of the dam. It should be realized that certain engineering aspects cannot be fully analyzed during a Phase I inspection. Assessment and remedial measures in the report include the requirements of additional indepth study when necessary.

Phase I reports include project information of the dam and appurtenances, all existing engineering data, operational procedures, hydraulic/hydrologic data of the watershed, dam stability, visual inspection report and an assessment including required remedial measures.

NAME OF DAM: UPPER NORTH RIVER NO. 76 (ELKHORN LAKE)
LOCATION: AUGUSTA COUNTY, VIRGINIA
INVENTORY NUMBER: VA. NO. 01506

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED FOR
NORFOLK DISTRICT CORPS OF ENGINEERS
803 FRONT STREET
NORFOLK, VIRGINIA 23510

BY

SCHNABEL ENGINEERING ASSOCIATES, P.C./
J. K. TIMMONS AND ASSOCIATES, INC.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of the Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (flood discharges that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the design flood should not be interpreted as necessarily posing a highly inadequate condition. The design flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

1	
FILED	1
DEC 1961	1
UNCLASSIFIED	1
Justification	
By	
Distribution/	
Availability Codes	
Avail and/or special	
Dist	A
	23
	CP

TABLE OF CONTENTS

Preface	i
Brief Assessment of Dam	1
Overview Photos	3
Section 1: PROJECT INFORMATION	4
Section 2: ENGINEERING DATA	8
Section 3: VISUAL INSPECTION	11
Section 4: OPERATIONAL PROCEDURES	13
Section 5: HYDRAULIC/HYDROLOGIC DESIGN	14
Section 6: DAM STABILITY	18
Section 7: ASSESSMENT/REMEDIAL MEASURES	23

Appendices

I	-	Maps and Drawings
II	-	Photographs
III	-	Field Observations
IV	-	Stability Analysis
V	-	Design Report
VI	-	References

Name of Dam: Upper North River No. 76 Dam, Va. No. 1506
State: Virginia
County: Augusta County
USGS Quad Sheet: Stokesville
Coordinates: Lat 38° - 19.6' Long 79° - 13.25'
Stream: Upper North River
Date of Inspection: December 13, 1978

BRIEF ASSESSMENT OF DAM

Upper North River No. 76 is a zoned earthfill structure about 824 ft long and 118 ft high. The principal spillway consists of twin 42-inch prestressed cylinder concrete pipes which extend through the structure. Water is discharged into the principal spillway through a reinforced concrete riser and is expelled into a riprap-lined stilling basin along the downstream toe of the dam. The emergency spillway is a 215 ft wide vegetated earth and riprap side channel spillway. The dam is located on the Upper North River about 8 miles southwest of the community of Stokesville, Va., and was constructed for flood control and recreation. The dam was designed and constructed under the supervision of U.S. Soil Conservation Service, cooperating with the Shenandoah Valley Soil Conservation District, City of Staunton. The City of Staunton, Va., has a special land use permit with the U.S. Forest Service for the construction and operation of the dam.

The dam will pass the probable maximum flood (PMF). Therefore, based on criteria established by the Department of the Army, Office of the Chief of Engineers (OCE), the spillway is rated adequate.

The visual inspection revealed no apparent problems and there are no immediate needs for remedial measures. The actual embankment structure appears to be similar to the "as built" drawings. We do recommend that vegetation be routinely controlled. The slopes, the crest of the structure, and the spillway should be mowed several times a year and existing small trees or saplings removed at least once a year. The slopes of the dam meet the requirements recommended by the U.S. Bureau of Reclamation for zoned earthfill dams. A summary of the stability analysis of the upstream and downstream slopes under rapid drawdown and steady seepage conditions was reviewed and assumptions, test data, and the resultant factors of safety were found to be acceptable.

Submitted by:

Original signed by
JAMES A. WALSH

James A. Walsh, P. E.
Chief, Design Branch

Approved:

Original signed by:

Douglas L. Haller


Douglas L. Haller
Colonel, Corps of Engineers
District Engineer

Recommended By:

Original signed by
ZANE M. GOODWIN

Zane M. Goodwin, P.E.
Chief, Engineering Division

Date: MAR 15 1979



OVERALL VIEW - ELKHORN LAKE
(View from the West)



OUTLET STRUCTURES - ELKHORN LAKE
(View from the East)

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
UPPER NORTH RIVER NO. 76 DAM VA. # 1506
(ELKHORN LAKE DAM)

SECTION 1 - PROJECT INFORMATION

1.1 General:

1.1.1 Authority: Public Law 92-367, 8 August 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of safety inspections of dams throughout the United States. The Norfolk District has been assigned the responsibility of supervising the inspection of dams in the Commonwealth of Virginia.

1.1.2 Purpose of Inspection: The purpose is to conduct a Phase I inspection according to the Recommended Guidelines for Safety Inspection of Dams (see Reference 1, Appendix VI). The main responsibility is to expeditiously identify those dams which may be a potential hazard to human life or property.

1.2 Project Description:

1.2.1 Dam and Appurtenances: Upper North River Dam No. 76 is a zoned earth-fill structure about 824 feet long and 118 feet high. The top of the dam is 28 feet wide and is at elevation 2084.0 ft M.S.L. Side slopes are 2.5 horizontal to 1 vertical (2.5:1) on the downstream side and 3:1 on the upstream side. Ten foot wide berms exist on the downstream and upstream slopes at El 2025 and 2017, respectively.

The principal spillway consists of twin 42-inch diameter prestressed cylinder reinforced concrete pipes, running through the dam. Discharge into the conduits is provided by a 9 x 10.5 ft

reinforced concrete riser with an inlet crest elevation of 2015.5 M.S.L. The riser has three inlets, each at a different elevation, located below the inlet crest. The inlets are used for low flow discharges or to drain the lake depending on sediment buildup. The riser is founded on sandstone and mudstone bedrock.

The emergency spillway, which is a vegetated earth channel having a bottom width of 215 feet, has a crest elevation of 2070.0 M.S.L., which is 14 feet below the top of the dam. The emergency spillway is in cut on the right side and on fill on the left side, and is located off the right end of the dam. The emergency spillway has a vegetative cover in all areas except where excavated rock forms the channel. The spillway has variable side slopes of about 1.25:1 to 2.5:1. The cut area of the emergency spillway is in weathered sandstone, shale, and mudstone bedrock. This information can be found in Appendix I, titled "Maps and Drawings", contained in this report.

1.2.2 Location: Upper North River Dam No. 76 is located on Upper North River about eight miles southwest of the community of Stokesville, Virginia. The reservoir formed by the dam is known locally as Elkhorn Lake. (See Sheet 1, Appendix I).

1.2.3 Size Classification: The dam is classified as a "large" size structure because of the dam height of 118 feet.

1.2.4 Hazard Classification: The dam is located in a rural and heavily forested area. However, based upon the close downstream proximity of Staunton Dam (the principal water supply source for the City of Staunton), the dam is assigned a "High" hazard classification. The hazard classification used to categorize dams is a function of location only and has nothing to do with its stability or probability of failure.

1.2.5 Ownership: The City of Staunton has a special land use permit with the U.S. Forest Service for the construction and operation of the dam.

1.2.6 Purpose: Flood Control and Recreation

1.2.7 Design and Construction History: The dam was designed and constructed under the supervision of the U.S. Soil Conservation Service. Responsibility for construction was by Shenandoah Valley Soil Conservation District and the City of Staunton, during 1962-1963. The dam was completed in 1965.

1.2.8 Normal Operational Procedures: The principal spillway is ungated, therefore, water rising above the crest of the drop inlet automatically is discharged downstream in quantities based on the inlet capacity. Similarly, water is automatically passed through the emergency spillway in the event of an extreme flood which creates a pool elevation above that of the emergency spillway.

1.3 Pertinent Data:

1.3.1 Drainage Areas: The original design (SCS) indicated a drainage area of 27.1 square miles which has been verified and found to be reasonable.

1.3.2 Discharge at Dam Site: Maximum known flood at the dam site occurred in 1972. Inflow was approximately 2400 CFS and all discharge was through the principal spillway.

Principal Spillway:

Pool Elevation at Emergency Spillway Crest 805 CFS
Pool Elevation at Crest of Dam 862 CFS

Emergency Spillway:

Pool at Crest of Dam 41,200 CFS

1.3.3 Dam and Reservoir Data: See Table 1.1, below.

Table 1.1 DAM AND RESERVOIR DATA

Item	Reservoir				
	Elevation	Area	Capacity		Length
	feet M.S.L.		Acre Feet	Watershed Inches (a)	
Crest of dam	2084.0	274	10,500(b)	7.6	1.4
Maximum pool, design surcharge	2074.7	227	8,090(b)	5.59	1.2
Emergency spillway crest	2070	221	7,020(b)	4.85	1.1
Principal Spillway crest	2015.5	53.5	3,066	3.5	0.5
Streambed at Center- line of dam	1966				

(a) Based on 27.1 sq.mi.

(b) From top of sediment pool

SECTION 2 - ENGINEERING DATA

2.1 Design: The dam was designed and constructed under the direction of the U. S. Soil Conservation Service (SCS) and was sponsored by the City of Staunton. As-built drawings and design data are available in the office of the State Conservationist, U. S. Soil Conservation Service, Federal Building, Room 9201, 5th and Marshall Streets, Richmond, Virginia 23240.

A subsurface investigation was conducted at the site by the SCS during the initial design stages. The investigation consisted of drilling 26 test borings and excavating 40 test pits. Subsurface profiles and a report of the investigation with foundation recommendations were prepared based upon permeability tests, test boring, and test pit data. The geologic report is available at the above referenced SCS office. Subsurface profiles are shown on Sheet 5, Appendix I.

The dam is a zoned, compacted earthfill embankment. The design recommendations shown on Sheet 1, Appendix I, specify that SM or SC materials be used in the core or Section No. 1 of the dam. On the downstream side, the core is blanketed with a 20 ft \pm thick zone of GM and GW material, designated Section No. 2. Section No. 2 is covered by Section No. 3, which consists of coarse GW material. The upstream portion of the core is overlain with finer GW material designated Section No. 4. A thin zone of finer GW material is located behind the downstream toe drain and is designated Section No. 4-A. The pervious downstream shell of Section No's. 2 and 3 control the phreatic surface.

A review of design drawings indicates the dam is founded on overburden and includes a cutoff trench which extends approximately 1 ft+ into bedrock. Both abutments are described as being water-tight, however, some water leakage was expected, principally through fracture zones in the rock beneath the dam. This was not considered critical in the design report and the possibility of piping was not believed a problem due to the hardness of the rock.

To control the phreatic water surface and to collect seepages, a rock toe drain was constructed along the downstream portion of the dam. This drainage system consists of a trench 10 ft wide at its base and a minimum 8 ft deep, filled with material graded in size from 1 to 24 inches. Twenty-three reinforced concrete anti-seep collars (see Sheet 8, Appendix I) were installed around the principal spillway pipes, under the entire dam and spaced at 24 ft intervals in order to control any potential piping problems along the pipes. Riprap gutters approximately 1.5 ft thick and ranging from 9 to 15 ft in width were constructed adjacent to both abutments to control local surface runoff.

The emergency spillway located adjacent to the right abutment was formed by making a side hill cut into residual soils and bedrock consisting primarily of very fine silty sandstone. Shale and mudstone were also probably encountered during excavation. Design drawings indicate compacted fill was placed locally to bring low areas in the spillway up to design grade. A berm was also constructed to form the left side of the spillway which is riprap lined.

The design report includes detailed laboratory test data describing the physical properties of the materials used to construct the embankment. Shear strength parameters used in design for the core, shell, and foundation material were determined by triaxial compression tests as follows:

<u>SECTION</u>	<u>SHEAR STRENGTH PARAMETERS</u>	
	<u>Angle of Internal Friction</u>	<u>Cohesion</u>
Core	$\phi = 23.5^{\circ}$	$C = 500 \text{ psf}$
	$\phi' = 31.5^{\circ}$	$C' = 350 \text{ psf}$
Shell	$\phi = 38.7^{\circ}$	$C = 0$
Foundation	$\phi = 36.0^{\circ}$	$C = 0$

The Modified Swedish Circle Method of Analysis was used and included evaluation of 1) the end of construction case, 2) the sudden drawdown case (I), and 3) the steady seepage case (III). Both effective and total strength parameters were utilized as dictated by the stability condition.

2.2 Construction: The construction records were not furnished by the SCS office in Richmond, but they are available from the SCS office in Washington, D.C.

2.3 Operation: There is no known operation and instrumentation procedure.

2.4 Evaluation: Engineering calculations are adequate and the design drawings are representative of the dam. There are no records available for dam performance.

SECTION 3 - VISUAL INSPECTION

3.1 General:

An inspection was made 13 December 1978 and the weather was partly cloudy with a temperature of 45°F. The pool elevation at the time of inspection was 2015.75 M.S.L. and the tailwater elevation was 1966.5 M.S.L., which corresponds to normal flows.

3.2 Findings: Field observations are outlined in Appendix III.

3.2.1 Dam and Spillway: There is tree and tall grass growth on the embankment and on the emergency spillway. Wet spots were observed along the drainage berm located at El 2026+ on the downstream slope of the structure. An area of damp soil was also located about 20 ft right of the left abutment and about 50 ft downstream of the drainage berm. Inlet structure and outlet works are in good condition.

3.2.2 Reservoir Area: Shoreline has no debris collection on banks or vegetation growth along shoreline in the water. Bank slopes are approximately 2:1 and show no sloughing or surface erosion. Inlet and outlet works show no deterioration.

3.2.3 Downstream Area: Staunton Dam is located approximately 9,000 feet downstream from Elkhorn Lake Dam and the U.S.G.S. mapping of the downstream area indicates no inhabited dwelling in the region.

3.3 Evaluation: Overall, the dam was in good condition at the time of inspection. However, some minor remedial measures are required. Uncontrolled growth encourages the development of

deep rooted vegetation. This type of growth can encourage piping within the embankment and undermine riprap protection. Also, excessive growth inhibits effective visual inspections of the dam. The embankment, including its crest, slopes, and emergency spillway, should be mowed at least once a year, but more preferably twice a year. Small trees presently growing near the left abutment and on the downstream slope should be removed.

Wet spots observed along the drainage berm on the downstream slope are probably the result of recent ponding from precipitation, and runoff along low areas in the berm. The general location of these wet spots is illustrated on Sheet 2 in Appendix I. These wet spots occur at El 2026+, while normal pool is at El 2015.5, therefore, they are not the result of seepage. The downstream berm slopes toward both abutments to the riprap gutters, thus providing an adequate drainage system for collecting runoff. If increased ponding continues in the future, local grading may be required to allow better drainage of this berm.

The area of damp soil illustrated on Sheet 2, Appendix I, is believed to occur because of seepage of the water ponded above in the drainage berm. This condition is not believed to be related to seepage through the dam.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 Procedures:

Elkhorn Lake is used as a source of water supply for the City of Staunton and for flood control purposes for Staunton Dam approximately 2 miles downstream. The normal pool elevation is maintained by a riser-type inlet acting as the principal spillway. During periods of below-normal flows, water flow is maintained through the dam by utilizing the valved inlets below the spillway crest. Operation of these inlets will lower the pool elevation below the spillway crest but will ensure flow to the City of Staunton water intake at Staunton Dam. During periods of above normal flows the pool elevation rises above the riser inlet increasing the flow through the inlet. Large increases in inflows which cannot be absorbed by storage are passed through the emergency spillway when the pool rises above elevation 2070.

4.2 Maintenance of Dam and Appurtenances: The maintenance is the responsibility of the City of Staunton and appears to be performed well. The operating appurtenances are in good working order, however, the vegetative growth on the embankment has not been maintained in the past year.

4.3 Warning System: No warning system exists. As noted, no inhabitable structures exist between this structure and Staunton reservoir.

4.4 Evaluation: The dam and appurtenances are in good operating condition and maintenance is being routinely performed except on the vegetative cover of the embankment. A mowing routine should be established and all trees removed from embankments.

SECTION 5 - HYDRAULICS/HYDROLOGIC DESIGN

5.1 Design: The Upper North River Dam (Elkhorn Dam) was designed by the Soil Conservation Service (SCS) as a multipurpose dam and complete hydrologic and hydraulic data is available. This structure is a Class "C" dam by the SCS classification method.

The crest of the riser of the principal spillway was established at elevation 2015.5 M.S.L., which would provide storage for a sediment pool and provide recreation (fishing and aesthetics). The capacity of the control structure was established to maintain a pool elevation below the emergency spillway during a 100-year flood. The emergency spillway is designed to accomodate the Probable Maximum Flood (PMF) without overtopping of the dam.

5.2 Hydrologic Records: There is a gaging station (1-6205) approximately one mile upstream of the structure on the North River measuring flow from 17.2 square miles. Records for this station have been maintained since 1947 by the U.S. Geological Survey. Some of the highest discharges recorded at this gaging station are 11,100 CFS in 1949, and 2400 CFS in 1972.

5.3 Flood Experience: The maximum pool elevation observed was reached during a storm in October 1972. The gaging station immediately upstream indicated a flow of 2400 CFS on October 5, 1972.

5.4 Flood Potential: The Probable Maximum Flood (PMF), $\frac{1}{2}$ PMF, and 100-year Flood hydrographs were developed by the SCS method (Reference 4, Appendix VI). Precipitation amounts for the flood hydrographs of the PMF, $\frac{1}{2}$ PMF, and 100-year Flood were taken from the U. S. Weather Bureau information (References 5 & 6, Appendix VI). Appropriate adjustments for basin size and shape were accounted for and emergency spillway hydrograph determination procedures as outlined in Reference 5; Appendix VI were used for the flood hydrographs. These hydrographs were routed through the spillway to determine maximum pool elevations.

5.5 Reservoir Regulation: The principal spillway is a riser-type control structure with a combined throat opening of 21 linear feet. This structure passes water through two 42-inch concrete pipes. The principal spillway maintains a normal pool elevation of 2015.5 and has gates at elevations 2005, 1995, and 1979 for purposes of dewatering and maintaining flow during periods of extreme low flow. During periods of flooding, the principal spillway is designed to accommodate the 100-year Flood with 9'± freeboard on the emergency spillway. Stream flows in excess of the 100-year Flood are passed through the emergency spillway at elevation 2070. For routing purposes the pool elevation at the beginning of the flood was assumed to be 2015.5. Reservoir stage-storage data and stage-discharge data were taken from the

SCS hydraulic calculations available. Floods were routed through the reservoir using the principal spillway discharge up to a pool storage elevation of 2070 and a combined principal and emergency spillway discharge for pool elevations above 2070.

5.6 Overtopping Potential: The predicted rise of the reservoir pool and other pertinent data were determined by routing the flood hydrographs through the reservoir as previously described. The results for the two flood conditions (PMF, $\frac{1}{2}$ PMF, and 100-year Flood) are shown in the following Table 5.1.

Table 5.1 RESERVOIR PERFORMANCE

	Normal Flow	Hydrograph		
		100-Yr	$\frac{1}{2}$ PMF	PMF
Peak flow, C.F.S.				
Inflow		9284	18,446	43,700
Outflow		708	803	36,232
Maximum Elevation, ft M.S.L.	2015.5	2048.14	2069.63	2082.94
Freeboard (ft)		35.86	14.37	1.06
Emergency Spillway (EI 2070)				
Depth of flow, ft	N/A	N/A	N/A	12.94
Duration, hours				1.0
Velocity, F.P.S.				20.75
Principal Spillway (EI 2015.5)				
Head, ft		32.64	96	110
Duration, hours	N/A	4.0	3.0	1.0
Velocity, F.P.S.		39	41.8	45
Tailwater Elevation, ft M.S.L.	1966.5*	1968.75	1968.9	1986.5

*This is the tailwater elevation observed during inspection and it corresponds to a normal flow.

5.7 Reservoir Emptying Potential: A 36-inch circular gate at elevation 1979.0 will drain the reservoir through two 42-inch aqueducts. Assuming that the lake is at normal pool elevation (2015.5) and an average inflow of 21 CFS is maintained, it would take approximately 2.5 days to lower the reservoir to elevation 1979.0. There are no methods for lowering the reservoir below this elevation.

5.8 Evaluation: Flood routing calculations indicate that the reservoir will rise to within one foot of the top of the earth embankment for the PMF and discharge for a period of 1 hour at a velocity of 17.5 feet per second. Hydrologic and hydraulic determinations of the project as prepared by the SCS appear reasonable. The appropriate spillway design flood is the PMF due to the "High" hazard conditions existing downstream. The emergency spillway will pass 100 per cent of the PMF.

Hydrologic data used in evaluation pertain to present day conditions with no consideration given to future development.

SECTION 6 - DAM STABILITY

6.1 Foundation and Abutments: Upper North River Dam No. 76 is founded on alluvial, colluvial and/or residual soils, all of which are underlain by the Hampshire Formation. The structure includes a 20 to 50 ft+ wide cutoff trench, which extends to bedrock. The principal spillway is founded primarily on sandstone, however, the outlet is underlain by sandy mudstone. The emergency spillway is in cut material, which included weathered sandstone, siltstone and mudstone. "As-built" drawings of these various areas are shown on Sheets 2 and 5, Appendix I. The test boring and test pit logs are included as Sheets 3 and 4, Appendix I.

The dam site is located within the Valley and Ridge Physiographic Province of Virginia, which is underlain by sedimentary rocks from Middle Cambrian through Early Mississippian age (see Reference 3, Appendix VI). In the Staunton area, the province consists of the Shenandoah Valley to the east and a series of much narrower valleys and intervening ridges to the west. The eastern portion of the province includes southeastward-dipping thrust faults and asymmetric folds, which are overturned to the northwest. More open folds are common in the central and western areas. Most ridges are "held up" by sandstones and conglomerates, whereas valleys are underlain by less resistant shales and limestones.

The dam site is underlain by rocks of the Hampshire formation of Late Devonian age. The Hampshire is approximately 2200 ft thick and includes moderately to thick-bedded, brown,

medium-grained, arkosic and micaceous sandstone and lumpy red to green mudrock and shale. The structure rests on the west limb of the West Mountain Syncline, approximately 2000 ft west of the synclinal axis, which strikes 40 degrees \pm to the northeast. The left abutment consists of a steep natural slope (70° \pm). The right abutment/emergency spillway is bound by a very steep manmade cut over 100 ft in height. This cut includes three 10 ft wide berms.

Sandstone bedrock is exposed in the left abutment, while sandstone, shale and mudstone are exposed in the emergency spillway cut. The sandstone is brown to gray in color, fine to medium grained, thin to massive bedded and close-jointed. The shale is brown to red in color. The geologic report describes bedrock strikes ranging from north to 70 degrees northeast and dips ranging from 9 to 15 degrees southeast. Measured attitudes in the field agree with those reported above. Wedge-shaped joint patterns were observed in the north abutment. These joints dip steeply and strike from 25 degrees northwest to 85 degrees northeast. No faults were observed in the field during this investigation and geologic maps of the area do not show the presence of faults in the immediate vicinity.

The potential for seepage does exist within the foundation since the dam is founded, at least in part, on sandy and gravelly soils. This material ranged in depth up to 40 ft[±] in the terrace deposits encountered in the right abutment. Rock was exposed in the stream channel. Field permeability tests show that this material is permeable to very permeable. In an attempt to control potential seepage, a cutoff trench was constructed and reportedly extends 1 ft[±] into firm bedrock. The geologic report describes the underlying bedrock as being quite impermeable; however, some seepage was expected through joint systems in the rock.

6.2 Embankment: The upstream slope is 3 horizontal to 1 vertical with crest at El 2084. At El 2017 the slope flattens to 10 horizontal to 1 vertical forming a berm for a vertical distance of 1 ft. The slope continues at 3 horizontal to 1 vertical to natural ground. Normal pool level is El 2015.5 or 0.5 ft below this berm. The downstream slope is 2.5 horizontal to 1 vertical with a drainage berm at El 2025. This 10 ft wide berm slopes towards the dam at 10 horizontal to 1 vertical. A sloping core consisting of SM and SC material with 3/4 horizontal to 1 vertical slope is provided to El 2070, the same grade as the crest of the emergency spillway. A typical section of the dam is included on Sheet 6, Appendix I. The core material is designated Section No. 1. The material comprising the downstream shell becomes progressively coarser ranging from GM and GW in Section No. 2 to GW in Section No. 3. The upstream shell designated Section No. 4 is also GW material with a finer gradation than the downstream shell. The downstream shell may be considered

pervious with drainage from the core or underseepage from the foundation passing to the downstream rock toe drain, Section 4A.

6.3 Evaluation:

6.3.1 Foundation and Abutments: Dam foundations must be evaluated on the basis of potential settlement, sliding and seepage. Excessive settlement of the dam is not believed to be a problem because the structure rests upon fairly competent bedrock and firm to compact alluvial, colluvial, and/or residual soils. Gradual consolidation of underlying soils would be expected during application of fill materials. The underlying soils probably had essentially fully consolidated under the applied load at the end of the construction period.

Sliding within the foundation bedrock does not appear likely based upon the design load and the nature of the Hampshire formation. In addition, a review of the geologic data indicates that there are probably no adversely oriented weak planes within the foundation rock that would act as a potential sliding plane.

Seepage was not considered a problem in design because the underlying bedrock was believed not to be susceptible to piping. Since construction reports were not available for review, an accurate determination of the foundation conditions under the cutoff trench is not possible.

The steep slopes which form the right side of the emergency spillway are cut into partially weathered sandstone, shale and mudstone, and were considered safe and stable at the time of investigation.

6.3.2 Embankment: The embankment slopes meet the requirement recommended by the U.S. Bureau of Reclamation for small zoned earthfill dams on stable foundation. Since no undue settlement, cracking or seepage was noted at the time of inspection, it appears that the embankment is adequate for maximum pool level with water at El 2074.7.

The stability analysis was performed with a section slightly different than actually constructed. However, the geometry of the dam corresponds very closely to "As-Built" drawings. The differences are not considered significant. The strength parameters described in Section 2 were used in the stability analysis. The report describing the engineering design data used in the stability analysis is included in Appendix IV. These data were reviewed along with the stability analyses and were found to be acceptable. The factor of safety of the upstream slope for the drawdown condition is 1.52 as given in Appendix IV. Reference 1, Appendix VI recommends a factor of safety of 1.2. The factor of safety for the downstream slope under steady seepage condition with drain (shell) at $c/b = 0.6$ is 1.82. The required factor of safety is 1.5 according to Reference 1.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES


7.1 Dam Assessment: The Upper North River No. 76 Dam at the time of inspection appeared sound and in a safe operating condition. The spillway will pass the PMF without overtopping the dam and is considered adequate. There is no apparent problem that requires immediate action for the normal pool conditions based on the visual inspection and a review of existing records. The actual embankment structure appears to be similar to the "as-built" drawings. Without the construction records, the conformance of the embankment material properties to design requirements cannot be assessed. The design factor of safety for rapid drawdown and steady seepage cases meet the requirement of Reference 1, Appendix VI, and the embankment slopes meet the requirements recommended by the U. S. Bureau of Reclamation, Reference 2, Appendix VI, for small zoned earthfill dams on stable foundations.

7.2 Remedial Measures: There is no immediate need for remedial measures; however, the following maintenance is suggested and should be initiated yearly. These measures are suggested for monitoring and maintenance purposes only.

7.2.1 The grass and weeds along the dam crest, slopes, and within the emergency spillway should be cut at least once and preferably twice a year. We would recommend maintenance in the early summer and fall.

7.2.2 Removal of all trees or saplings from the
above described areas should be accomplished every
year.


APPENDIX I
MAPS AND DRAWINGS



SCALE 1" = 2000'
STOKESVILLE, VA.
SW/4 PARNASSUS 15' QUADRANGLE

LOCATION
MAP

SHEET 1



NOTE
 CLEARING AND GRADING LIMITS
 ON GENTLE SLOPES 15 FEET BEYOND
 NORMAL POOL ELEVATION
 ON STEEP SLOPES 1 FT ABOVE NORMAL
 POOL ELEVATION AS INDICATED BY DASHED LINE


GENERAL NOTES

1. AREA UNDER FILL, BOWEN AREAS, AND EMERGENCY SPILLWAY TO BE CLEARED AND GRABBED.
2. ENTIRE NORMAL POOL AREA IF BE CLEARED AND GRABBED.
3. ALL CONNECTED FILL SHALL BE CLASS. B-2 AND C, PLACED AS SHOWN ON PLANS AND AS DIRECTED BY ENGINEER IN FIELD.
4. THERE ARE APPROXIMATELY 35.7 ACRES OF LEAVING, FERTILIZING, SEEDING PREPARATION AND MULCHING THIS INCLUDES THE ENHANCEMENT ABOVE THE NORMAL POOL, EMERGENCY SPILLWAY SIDE SLOPES AND BOTTOM, AND ANY OTHER DISTURBED AREAS.

LEGENDS

- 2000 --- CONTOUR LINE
- NORMAL POOL LINE ELEV. 2015.5
- STREAM
- LIMIT OF CLEANSING & GRADING
- TEST PIT ON SPILLWAY (SOIL)
- TEST PIT - DISTURBED SAMPLE
- TEST AT FROM WHICH CONSTRUCTION MATERIAL WILL BE OBTAINED AND SUBSCRIPT INDICATES SECTION IF DAM WHERE IT WILL BE USED

⊙ WET AREAS ON DRAINAGE BERM



AS BUILT SHEET 2

UPPER NORTH RIVER WATERSHED
OF THE POTOMAC RIVER WATERSHED PROJECT
MULTI-PURPOSE DAM NO. 7
AUGUSTA AND ROCKINGHAM COUNTIES, VIRGINIA

SITE LOCATION MAP

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

Designed by H. W. WILSON, R.S. BARRETT JR. 8-62	Drawn by L. J. GIFFMAN 8-62	Checked by [Signature] 8-62	Project No. VA-472-P 2
--	--------------------------------	--------------------------------	---------------------------

1. Silty mudstone, red (dark) with some gray mottling (massive).
2. Gray silty mudstone. Very hard mass. 1' to 3'.
3. 3.5 - 13.5 interbedded very fine sandstone (gray to black) and mudstone (gray to black). Sand between 3.5 - 13.5 sand from 10' to 13.5' planes to indicate water phase.
4. 33.5 - 34 basically a silty mudstone dark red with some very fine sandstone and siltstone interbedded with the massive mudstone.
5. Some gray mottled some of very fine sandstone at 34, 36, 56, 62, 66 and 72'.

1. Silty mudstone very hard with some of sandstone and black mudstone. Some carbonaceous. Black stain along joint faces. Very hard and impermeable in bedrock.
2. Sandstone, siliceous, almost a quartzite, some black and iron stain along joints abundant carbon flakes and some at 17-18' and 21-23' (almost coal seams).
3. Abundant iron stain at 25' (evidence of water movement through this zone).
4. Mudstone, black very impermeable, core broken up between 41-42' leakage zone. Some splits of siltstone and very fine sandstone present but not enough to note location.

Gravel, silty to well graded, rounded to subrounded pebbles to boulders. (See notes)

Quartzite very fine, some carbon along bedding 12' - 13' broken up along joints. Iron stained.

Mudstone silty black, with some some splits at 18 - 21 and 22 - 23, rock to very impermeable. No evidence of leakage below 16'.

1. Silty sand with interbedded sand.
2. Sandstone very fine to silty, some silty. Abundant carbon flakes and some 21-23' (carbon seams and pyrite) also at 21-23.5. Sand is very impermeable and this is shown by pressure testing data. These don't appear to be any water in rock as no pore space is present.

1. Gravel well graded, some boulders.
2. Mudstone, silty black to dark gray, some evidence of sand but not enough to notice and black staining along joint faces. Rock is hard and impermeable.

1. Transitional zone of mudstone and silty sandstone.
2. Silty quartzite, very fine and hard, pure quartz sand with sparse mica. Thin mudstone split with pyrite at 47'. This rock is very impermeable and competent.

Some SiO₂ along bedding planes at 65', 66, 66.5, 74, 76'.

BN-9 Elev. 2106.03'

1. 74 - 76 Black siltstone massive.
2. 76 - 90 interbedded massive red mudstone and gray to black very fine sandstone and siltstone.
3. Same as above.
4. Red massive mudstone with interbedded siltstone (gray).
5. 90-103 Gray to black massive very fine sandstone, SiO₂ seen at 91'.
6. This sandstone has been fractured but these fractures are filled with SiO₂.
7. This zone is hard like whole section. Quartz seen at 95.5. Some evidence of H₂O movement.
8. 103-107 very fine very hard mudstone with sandstone, almost a quartzite and mudstone (black).
9. 107-120 very fine gray sandstone, some SiO₂ seen scattered throughout, filled joint between 107-111.
10. Last run from 116.8 - 120 came out of core barrel in one piece. Had to be broken to put in core box, very hard well indurated. Silica cemented very fine sandstone and some carbonaceous material in lower sandstone and some Fe₂O₃ (Manganese or pyrite).

1. Highly weathered siltstone, some clay and sand, forms a sandy silt. M. or clay Cl. Blow Count 8-10-31.
2. Same as above. Blow Count 14-26-41.
3. Highly weathered sandstone, silty with pebbles of hard sandstone forms an M. Blow Count 12-26-36.
4. Same as above but finer with little or no pebbles. Blow Count 16-28-42.
5. Weathered siltstone to sandstone, very fine, forms a M. to M. Blow Count 18-29-52.
6. Sandstone weathered, very fine to silty, massive, some mica, black stain on joint faces.

1. Mudstone-siltstone yellow, some mica.
2. Sandstone, very fine to silty, tan black stain on joint faces, one foot mudstone split at 47'.
3. Mudstone, dark red, massive, all rock is weathered in this hole.

BN-10 Elev. 2128.3'

1. Sand to silty gravel, tan, very fine sandstone pebbles to cobbles.
2. Highly weathered silty sandstone.
3. Weathered silty sandstone forms a silty sand to sandy silt.
4. Mudstone, silty.
5. Sandstone weathered massive, siliceous in 34-43 hard, almost a quartzite. Some black stain along joints, some mica. Sandstone is very fine to silty. 47-50 abundant carbon flakes and thin coal seams.

1. Mudstone green.
2. Sandstone, siltstone and mudstone interbedded, very weathered, some iron stain.
3. Mudstone green to gray, very fine.
4. Sandstone, siliceous, massive, jointed black stain on joint faces. (This zone may be too hard to rip).
5. 67-66 abundant carbon flakes and seams.

1. Mudstone, silty gray-green, weathered.
2. Mudstone silty, red, massive, this rock should rip with difficulty.

BN-19 Elev. 1987.56

1. Gravel, silty to sandy, rounded pebbles to boulders.

Quartzite very hard, silty, some conglomerates at 11 foot like BN-20.

1. Mudstone, silty black, abundant iron stain in some 15-26'.
2. Sandstone split at 19-20'. This mudstone shows some evidence of weathering, but is very impermeable and competent. Some some of sandstone and siltstone but basically rock is mudstone. Some conglomerates at bottom of hole with pebbles of quartz and muddy matrix.

BN-11 Elev. 2055.6'

1. Silty sand with pebbles, product of weathered sandstone tan to brown. Blow Count 14-26-41.
2. Same as above, forms almost a silty all weathered very fine silty sandstone. Blow Count 17-40-58.
3. Highly weathered sandstone with abundant pebbles forms an M. Blow Count 17-21-46.
4. Sandstone weathered, dark red, silty, broken up, some mica.

BN-20 Elev. 2015.8

1. Gravel with sand and silt alluvial and colluvial terrace. Silty permeable. Blow Count 34-36-56.

1. Same as above but gravel fraction is coarser and less rounded. Blow Count 31-31-34.
2. Gravel well graded to silty, sandstone and siltstone pebbles more permeable than above because of the smaller amount of silt. Blow Count 35-31-43.
3. Same as above, Blow Count 35-31-43.
4. Blow Count for last two samples for last 0.5 foot is due to pebbles (see above).
5. Gravel with silty sand matrix, some of gravel breaks out to top sand. Blow Count 37-37-56.
6. Same as above. Blow Count 38-38-56.
7. Weathered sandstone, refuted, Blow Count 41-102-105-112.
8. Quartzite very fine light gray massive some iron stain at 11-12' and 34-37' very conglomeratic and impermeable, some carbon flakes and some mica.
9. Sandstone, silty gray to black, some weathering, bottom sandstone and mudstone at 41'.
10. Quartzite, some blackening in some zone, some conglomerates at 41'.
11. Last cavity at 47', silty, some weathering, some evidence of weathering, some conglomerates at bottom of hole with pebbles of quartz and muddy matrix.

BN-12 Elev. 2081.7

1. Highly weathered sandstone very fine to silty, forms a sand, with pebbles. Blow Count 14-26-41.
2. Highly weathered sandstone, forms a very fine sand. Blow Count 16-31-46.
3. Highly weathered sandstone, forms a very fine sand, fragments of mudstone. Blow Count 16-31-46.
4. Highly weathered sandstone with abundant fragments with mica. Blow Count 16-31-46.
5. Sandstone, very fine to silty yellow-brown, some mica, weathered.
6. Mudstone, red.
7. Sandstone, siltstone and mudstone interbedded, red-brown black stain on joints.
8. Mudstone, red massive.

BN-21 Elev. 2022.46

1. Silty sandy gravel, M. to subangular. Blow Count 34-36-56.
2. Silty gravel with subangular fragments quite permeable. Blow Count 31-34-56.
3. Well graded to silty gravel rounded to subrounded pebbles. Blow Count 31-34-56.
4. Well graded to silty gravel rounded to subangular pebbles. Blow Count 34-36-56.
5. Gravel to clayey gravel rounded to angular pebbles. Blow Count 35-36-56.
6. Silty to clayey gravel, to subangular pebbles of M. siltstone and mudstone. Blow Count 35-36-56.
7. Silty sand with pebbles, rounded to angular pebbles. Blow Count 35-36-56.
8. Silty gravel formed from weathered silty sandstone. Blow Count 37-38-56.
9. Sandstone very fine, some 60 feet, some carbon flakes and mica, light gray with some iron stain.
10. Siltstone, muddy with some in places, dark gray to black impermeable hard rock, some fine mica flakes.

BN-17 Elev. 2007.86

1. Silty gravel with sandstone pebbles to cobbles. Blow Count 8-5.5' - 24-17-28.
2. Silty gravel same as above. Boulders at 10 feet. Blow count 160 blows for 0.3'.
3. Same as above, blow count 16-21-13.
4. Same as above, some very fine evidently abundant boulders. Blow Count 20-20.5 - 114 with a 1609 hammer and 20.3-21.5 using a 3009 hammer. Blow count was 15 and 23.
5. Silty to sandy gravel, M. or G., this zone is quite permeable so probably a G. Blow Count 11-10-14.
6. Well graded gravel, permeable, may be some weathered bedrock. Blow Count 16-35-36.
7. Mudstone, red, massive, very hard, some thin splits of very fine sandstone, sparse pyrite.
8. Interbedded sandstone, siltstone and mudstone massive to laminated, abundant mica along laminae (This rock is present in the other section hole.)

BN-18 Elev. 1984.93

1. Silty gravel with pebbles to cobbles.
2. Mudstone, silty, black, some stain at 10, 13, & 14'. Silty and sandy in places, some pyrite, very impermeable and competent.

1. Quartzite same as in the mudstone.
2. Mudstone, silty, massive, impermeable very hard.

Blow count is for 0.5' increments.

Ref. No. 3336

• 30 highly trained technicians

[illegible]

weathered.

MM-14 Elev 3288.6

- 5 Leaves and top soil
- 6 Silty sand with about 10 percent clay with small rounded pebbles weathered sandstone. Blw Count 3.5 - 74, 2.5-b in 30' or more
- 7 Silty sand as above - Blw Count 10-11.5 in 5' increments 13-21 This material is weathered sandstone.
- 8 SN Weathered sandstone, silty, from 11.5 to 15 but not no good cutting were very fine, sand, silty. Blw Count 40-3-30. Weathered sandstone forms a sand with angular pebbles.
- 9 SN Weathered sandstone, silty.

Christone, et

102 GN Weathered sandstone, colluvial and alluvial material forms a
OR 55 ft. 10-11-77 22
103 GN Very fine sandstone, colluvial and alluvial material forms a CH or This
stone is slightly gravelly to
104 GN Weathered sandstone a
as gravel. Blue Count 47-52-57
OR 59 ft.
105 GN or Weathered sandstone
colluvial sand and gravel. CH
GN. Blue Count 30-45-66
106 GN Weathered fine sandstone, g
mable, forms a fine to co
ably BN. Blue Count 41-75-77
107 GN Fine to hard sandstone, v
fine to silty forms a CH or
Blue Count 43-28-79

**U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE**

Page	Date	Approved by
N. A. WILSON, R. C. BARNES JR. 8-62	File	
WILLIAMS "HARDHILL", JIM S. FENNEL 8-62	File	
J. S. COFFMAN		
Trace		
Sheet	Drawing No.	
7		
of 19		VA-472-P
R.F. Fowder	N-1243	

SHEET 3

EN-103 Elev. 2016.49

See p. 604
Colluvial and alluvial material from weathered very fine silty sandstone forms a EN or GN. Slow Count 17-20-43.
EN or GN Colluvial silty and clayey sandy sand and gravel. Slow Count 21-24-31.
EN Silty sand with some clay and pebbles from weathered sandstone. Slow Count 17-16-23.
EN Silty, sandy gravel G4 Slow Count 23-37-43.
24 Weathered sandstone had to core drill got one foot of core.

TP-107 Elev. 1995.6

EN or GN Silty gravel to silty sand.
EN Silty gravel with siltstone and sandstone pebbles to boulders.

TP-126 Elev. 2001.4

EN or GN Silty sand and gravel, rounded alluvial, water at 5'.

TP-132 Elev. 2007.9

EN or GN Well graded to silty gravel, rounded to sub-rounded, slowly permeable, water at 4 feet.
EN or GN very permeable, 50% greater than 6'.

TP-140 Elev. 2011.7

EN Silty to well graded gravel, water at 6'.
Field sample over 12" 09 0Z
6 to 12" 579 12Z
3 to 6" 739 10Z
Less than 3" 3129 71Z
Total Wt. 4429
EN-140-1 Sample consists of the material less than 3" size.

TP-401

EN or GN Silty to well graded, water at 3'.
Field sample over 12" 09 0Z
6 to 12" 579 12Z
3 to 6" 739 10Z
Less than 3" 3129 71Z
Total Wt. 4429
Bedrock - Quartzite silty sandstone.

EN-104 Elev. 1991.24

EN Colluvial and alluvial silty sand with pebbles. Slow Count 13-24-42.
EN Colluvial silty sandy gravel with angular pebbles. Slow Count 14-23-19.
EN Same as above but less silt and pebbles. Almost an SP. Slow Count 3-3-3.
EN Weathered sandstone forms a silty sand, brown to gray.
EN Weathered sandstone refusal at 24' Slow Count 20-44-100.

TP-108 Elev. 1994.6

EN-108-1
Silty gravel, rounded alluvial pebbles to cobbles. Water at 11' G.M.

TP-125 Elev. 2000.0

EN-125-1
EN or GN, rounded alluvial pebbles to cobbles, water at 6'.
Field sample over 12" 09 0Z
6 to 12" 579 12Z
3 to 6" 739 10Z
Less than 3" 3129 71Z
Total Wt. 4429
EN-125 & 126-1 Sample consists of material less than 3" size.

TP-133 Elev. 2012.6

EN or GN, alluvial, rounded pebbles to cobbles, hole dry, very slowly permeable.

TP-141 Elev. 2013.6

EN Sand, well graded to silty sand, pebbles to cobbles, water at 5'.

TP-402

EN or SP Well to poorly graded sand to gravel.
EN or GN Well graded to silty gravel.
Field sample over 12" 09 0Z
6 to 12" 579 12Z
3 to 6" 739 10Z
Less than 3" 3129 71Z
Total Wt. 4429

EN-105 Elev. 2040

EN Very fine brown, silty sand with some rounded pebbles alluvial and colluvial sand. Slow Count 10-21-26.
EN Same as above but pebbles are angular and some clay is present. Slow Count 33-60-71.
EN Same as above but greater percentage of silt almost an ML. Slow Count 31-24-20 Pebbles are sandstone, siltstone and sandstone.
EN Same as above but may be enough pebbles to make a GN-EN. Slow Count 49-45-40.
EN Same as above but less fines but still a silty sand with pebbles. Slow Count 33-20-17.
EN or GN Very fine silty to clayey sand with pebbles, this is almost an ML from slow count 9-7-10.
EN Silty sand with pebbles, like above. Slow Count 20-44-67.

TP-109

EN-109-1
EN or GN Silty sand to gravel, gray brown colluvial.
EN or GN Silty sand to gravel brown.
EN or GN Silty sand to gravel light brown.

TP-124 Elev. 2004.6

EN-124-1
EN or GN doesn't appear to be silty. Water at 7 feet, gravel is rounded to sub-rounded, may be good for filter.
Field sample over 12" 09 0Z
6 to 12" 579 12Z
3 to 6" 739 10Z
Less than 3" 3129 71Z
Total Wt. 4429

TP-134 Elev. 2018.4

EN Silty sand with pebbles.
EN Silty sand with pebbles to cobbles, no water.

TP-209 Elev. 2096

EN Silty sand, gray brown residual sandstone.
EN or GN Silty sand, tan with pebbles to cobbles, weathered silty sandstone.
EN or GN Weathered silty sandstone forms a GN or EN.

TP-101 & 102

EN-101 & 102
EN
EN Gravel angular, well graded, colluvial and alluvial, very few fines.
Field sample over 12" 09 0Z
6 to 12" 579 12Z
3 to 6" 739 10Z
Less than 3" 3129 71Z
Total Weight 7549
EN-101 & 102 Sample consists of material less than 3" size.

TP-119 (See EN-19)

EN Silty gravel rounded pebbles to cobbles some bigger than 3".
Field sample over 12" 09 0Z
6 to 12" 579 12Z
3 to 6" 739 10Z
Less than 3" 3129 71Z
Total Wt. 4429
Bedrock at 9' see EN-19.

TP-127 Elev. 2006.7

EN or GN Silty to well graded gravel, alluvial like TP-127 but not as clean and well rounded. Water at 5', permeable.

TP-135 Elev. 2015.0

EN Silty gravel, black.
EN or GN, water at 5'.

TP-218 Elev. 2125.2

EN or GN residual silty sandstone.
EN Highly weathered sandy siltstone, forms a pebbly EN.
EN or GN Weathered thin bedded silty sandstone, forms a EN or ML can be ripped deeper.

TP-103 (See EN-103)

EN-103-1
EN Silty gravel, cobbles 20 percent by weight.

TP-120

EN-120-1
EN Silty sand very fine and cobbles.
EN Silty gravel.
EN Silty sandstone over 12".
Field sample over 12" 09 0Z
6 to 12" 579 12Z
3 to 6" 739 10Z
Less than 3" 3129 71Z
Total Wt. 4429
Sample consists of material less than 3" size.

TP-128 Elev. 2007.7

EN or GN Silty to well graded TP-127, alluvial gravel, permeable rounded to sub-rounded pebbles to cobbles, water.

TP-136 Elev. 2020.7

EN Silty gravel reddish brown alluvial pebbles to cobbles.
EN Silty gravel with very little hole dry.

TP-211

EN-211-1
EN Silty sand, gray brown silty sandstone.
EN or GN Silty sand, tan with pebbles to cobbles, weathered sandstone.
EN or GN Weathered silty sandstone forms a GN or EN.

TP-104 (See SM-104)

CH Silty gravel, alluvial and colluvial with rounded to angular pebbles to boulders. Water at 7'.

TP-104 SM-Split Spoon
J-Glass Jar

TP-105 (See SM-105)
SM-105-1

CH Silty gravel, with no cobbles larger than 6" most are less than 3" or 1/2 residual CH to SL, some weathered to fine sand & silt, with pebbles to boulders.
CH or SL weathered, very fine sandstone to siltstone with siliceous nodules 12" See SM-105

TP-105 Elev. 2031.8
SM-105-1

CH Colluvial silty gravel, brown with angular to subrounded, sandstone to siltstone cobbles, 50% greater than 3" about 10 percent greater than 12". Very little clay.

TP-121 Elev. 1996.3
SM-121-1

CH Silty to well graded gravel, rounded, silty. Water at 6'.
Field sample over 12" 0 CH
6-12" 1250 362
3-6" 900 262
Less than 3" 1550 471
Total Wt. 3400
*Sample consists of material less than 3" size.

TP-122 Elev. 1993.6

SM or SP clean alluvial Silty gravel rounded cobbles to boulders
Cobbles and boulders Water at 6'. See 121-1

TP-123

SM or SP Silty gravel, rounded to subrounded pebbles to boulders. See 121-1

TP-129 Elev. 2003.6

SM or CH Silty sand to gravel alluvial and colluvial CH or CH
CH or CH alluvial, sub-rounded to rounded. Water at 6', slowly permeable.

TP-130 Elev. 1997.4
SM-130-1

CH Silty to well graded gravel, sub to well rounded, slowly permeable. Water at 6'.
Field sample over 12" 0 CH
6-12" 1400 410
3-6" 840 212
Less than 3" 1200 308
Total Wt. 4030
*Sample consists of material less than 3" size.

TP-131 Elev. 2001.6

SM Silty sand with pebbles to cobbles, alluvial, slowly permeable, rounded to sub-rounded
CH or CH well graded to silty gravel, water at 5' See TP-126

TP-137 Elev. 2020.2

SM Silty sand with pebbles, brown to black
CH Gravel, silty with water at 6' 6"

TP-138 Elev. 2008.5
SM-138-1

SM Silty sand with pebbles and cobbles
CH Gravel, well graded to silty Water at 5'
Field sample over 12" 950 191
6-12" 610 81
3-6" 950 191
Less than 3" 2050 372
Total Wt. 5160
*Sample consists of material less than 3" size.

TP-139 Elev. 2006.8

CH or CH Silty to well graded gravel. Water at 5'

TP-212 (See SM-10)
SM-212-1

SM or CH Silty sand to gravel, tan residual silty sandstone.
SM Highly weathered silty sandstone, SM with pebbles.
SM or SL weathered very fine silty sandstone forms a SM or SL with pebbles.

TP-213 (See SM-13)
Elev. 2110.06
SM-213-1

SM or CH Sandy silty gravel, dark brown
CH or SM Highly weathered very fine silty sandstone, brown to red brown very fine, pieces rough residual pebbles and cobbles to form a CH
CH or SM weathered very fine sandstone to siltstone, siliceous nodules and residual sandstone pebbles to cobbles to form a silty gravel.

TP-215 Elev. 2060.3
SM-215-1



SM or CH Highly weathered flaggy var. fine sandstone forms a SM or CH
CH or SM weathered silty sandstone forms a CH or SM
All holes in spillway were dry and well drained.

NOTE: SOIL & ROCK DESCRIPTIONS DETERMINED BY VISUAL INSPECTION
CLASSIFIED AND RECLASSIFIED BY VISUAL INSPECTION
GEOLOGICAL INVESTIGATION DATE: DEC 61 - JAN 62 - FEB 62


AS BUILT SHEET 4

UPPER NORTH RIVER WATERSHED
OF THE POTOMAC RIVER WATERSHED PROJECT
MULTIPLE PURPOSE DAM NO. 76
AND ROCKHAW TUNNEL PROJECT
SOILS INFORMATION

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE



TYPICAL EXCAVATION SECTIONS OF LUTOFF TRENCH



PROFILE ALONG & OF VEGETATED WATERWAY

SCALE: HOR. 1" = 40.0'
VERT. 1" = 8.0'

SHEET 5

**UPPER NORTH RIVER WATERSHED
OF THE POTOMAC RIVER WATERSHED PROJECT
MULTIPLE PURPOSE DAM NO 76
AUGUSTA AND ROCKINGHAM COUNTIES, VIRGINIA
PROFILES**

**U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE**

Designed by WILSON - BARNES & GORDON

Drawn by L.S. COFFMAN AUG 62
W.H. MORGAN OCT 62

Checked by *W.H. Morgan*

Approved by

Title

Date

Sheet

of 19

Drawing No. **VA-472-P**

Form SCS-316 November 1958

TYPICAL SECTION OF OUTLET CHANNEL

THE DESCRIBED ACCESS ROAD WILL BE USED FROM P. 1 AT 95' TO THE ELEVATION OF THE NORMAL FLOOD DRAINAGE AND A LOW WATER CROSSLING OVER WHITE OAK LUM WILL BE PROVIDED AS SPECIFIED BY THE U.S. FOREST SERVICE.

"HF SURVEY GUNTS INDICATED FIRM TO 50 FT (APPROX)
TO THE EMERGENCY SPILLWAY ENTRANCE WILL NOT BE
CONSTRUCTED OR USED IN THIS PROJECT.

U.S. FOREST

SPECIAL USE PERMIT BOUNDARY IS DESIGN
HIGH WATER ELEV 2079.7

DESIGN HIGH WATER ELEV 2079.7 236.0 ACRES
FLOOD POOL AT SPILLWAY ELEV 2000 221.2 ACRES

U.S. FILE

1. ALL ORGANIC MATERIAL, LEASE OIL AND SOLIDS, SHALL BE REMOVED FROM UNDER THE FILL AREA, AS DIRECTED BY THE ENE-MFL.

2. ANY INTERMIXING OF SOFT TALUS MATERIAL,
SANDS IF REMOVED FROM UNDER THE FILL AREAS
AS DIRECTED BY THE ENGINEER.

9 ALL STEEP SLOPE AND STEEP ROCK FACES, SHALL BE CUT BACK TO A 1:1 SLOPE AS DIRECTED BY THE ENGINEER.

4. THE EMBANKMENT SIDE SLOPES SHOWN
ARE SETTLED SLOPES. CONSTRUCTED
SIDE SLOPES WILL BE ADJUSTED
TO MEET THESE REQUIREMENTS.

5. EARTH SURFACE OF DAM TO BE FINISHED BY ROCK RAKING AND SMOOTHING.

COULD BE EXCESS OF 12" IN SIZE WILL
BE L.A. COLUMN SECTION NO. 4 &
DISPOSED OF IN THIS AREA.
FORM A (CABLE MOUNTED)
LOOSE AT LEAST 10' IN
THICKNESS.

SECTION NO. 1 SILTY SAND(S)

SHELL 1000 7 10 11 12 SAND (10) 4
10 105 109 210 212-213 OUT 7
(418 501 5 1000 111)

SECTION 4: 2

SMALL FOUNTAIN OF
TODS - 125 6420
60 60
(51)

SECTION No 4

SECTION


~~SECRET~~ ~~NOFORN~~ ~~S.S.~~

15


SECTION N° 4A-

TYPICAL SECTION OF DAM

ADJUSTED ELEVATIONS



SECT. 1 (A) : SAND OR SILT MATERIAL (B-1)
 SECT. 1 (B) : LIME STABILIZED OR MATERIAL (B-2)
 SECT. 1 (C) : SAND TO ADJUSTIVE OR MATERIAL (B-1)
 SECT. 3, 4 : SAND FILL



NOTE: LOCK EXCAVATED FROM THE EMERGENCY (P. 10) THAT IS SUITABLE FOR EMERGENCY WATER, AS DETERMINED BY THE ENGINEER, ONLY BE PLACED IN SECTION 1 (B) OF THE DAM. IN THE EMERGENCY, ONLY MAY BE PLACED AS COMPACTED EARTH FILL. THE REMAINDER OF THE EXCAVATED DAM BE DISPOSED OF ON THE "SAND FILL" AND TOE OF THE DAM AND ON THE "SAND FILL" OF THE DAM. EXCAVATION OF THE DAM BE PLACED ON THE "SAND FILL" AND IN THE AMOUNT "REJECTED" BY THE ENGINEER FOR THE "SAND FILL" AND BE SUBSIDIARY TO LOCK EXCAVATION.

2 SANDCLAY (SC)

THE LOGS OF
 FROM 1ST TO 12TH
 B-2 FILL

RAVELLY (G&W)

ALL (G&W) MATERIAL BE REPRESENTED BY THE LOGS OF
 TO 1ST AND 12TH FROM 1ST TO 12TH MATERIAL LARGER THAN
 TO 12TH FROM 1ST TO 12TH MATERIAL LARGER THAN 1/2 IN.
 (SEE SPEC. 5-B "SAND FILL", CLASS B-2 FILL)

SECTION N° 3

ALL (G&W) COARSE MATERIAL (G&W) FROM THE DESIGNATED BOUNDARY
 AREAS AS REPRESENTED BY THE LOGS OF TO 1ST TO 12TH FROM 1ST TO 12TH
 TO 12TH FROM 1ST TO 12TH MATERIAL LARGER THAN 1/2 IN.
 (SEE SPEC. 5-B "SAND FILL", CLASS B-2 FILL)

SECTION N° 4 AND 4A

ALL (G&W) FINEST MATERIAL (G&W) FROM THE DESIGNATED BOUNDARY
 AREAS AS REPRESENTED BY THE LOGS OF TO 1ST TO 12TH FROM 1ST TO 12TH
 TO 12TH FROM 1ST TO 12TH MATERIAL LARGER THAN 1/2 IN.
 (SEE SPEC. 5-B "SAND FILL", CLASS B-2 FILL)

ROCK TOE

ROCK TOE

ROCK TOE

MATERIAL GRADED IN SITU
 FROM 1ST TO 12TH

AS BUILT SHEET 6


UPPER NORTH RIVER WATERSHED
 OF THE POTOMAC RIVER WATERSHED PROJECT
 MULTIPLE PURPOSE DAM NO. 7
 AUGUSTA AND FREDERICKS COUNTY, VIRGINIA
 RESERVOIR AREA MAP


U.S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE

W. W. WILSON, R. C. BARNES JR. 6-66

5 COPY MAY

W. A. Rasmussen 3 VA-472-P2





AS BUILT SHEET 7

UPPER NORTH RIVER WATERSHED OF THE POTOMAC RIVER WATERSHED PROJECT MULTIPLE PURPOSE DAM NO 76 AUGUSTA AND ROCKINGHAM COUNTIES, VIRGINIA PROFILES	
U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	
Designed WILSON - BARNES <small>JUNE 62</small> Drawn L.S. COFFMAN <small>AUG 62</small> C.T. BARNHART <small>OCT. 62</small> Check W.L. A. [Signature] <small>1-63</small>	Approved by _____ _____ _____ _____ _____
VA-472 - 7	



PLAN
SCALE 1" = 30.0'

42" I.D. REINF. CONC. WATER PIPE
70 16'-0" SECTIONS
2 SIPCOT RING WALL FITTING

TOTAL - 1750.67

44 SECTIONS
J-4 THRU J-40
AND
J-27 THRU OUTLET

PRESSURE HEAD = 103'
LOAD = 45,700 LBS. PER LIN. FT. BASED ON O.D. OF 55"
MIN 3 EDGE BEARING STRENGTH FOR 0.001" CRACK
EQUALS 15,700 LBS. PER LIN. FT. FOR PRESTRESSED
PIPE ANWWA C-301

14 SECTIONS
J-40 THRU J-27

PRESSURE HEAD = 103'
LOAD = 111,720 LBS. PER LIN. FT. BASED ON O.D. OF 50"
MIN 3 EDGE BEARING STRENGTH FOR 0.001" CRACK
EQUAL 26,400 LBS. PER LIN. FT. FOR PRESTRESSED
PIPE ANWWA C-301

REINF. CONC. RISER
CLASS "B" CONC. TYPE I
DETAILS SHEET 13, 14 & 15

CATWALK DETAILS SHEET 10

RISER CREST
ELEV. 2015.5

2' DIA. SLUICE
GATE DETAILS SHEET 12

RISER FLOOR
ELEV. 1970.5

SIPCOT RING WALL FITTING
DETAILS SHEET 11

ELEV. 2014.0

ELEV. 2017.0

INTL. BEEP COLLAR
DETAILS SHEET 13

PIPE ENLARGEMENT

64.0'

23 REINF. CONC. COLLARS @ 24.0' CLASS "B" CONC. TYPE II DETAILS SHEET 14

307.53'

624.33'


PROFILE ALONG E OF PRINCIPAL SPILL
SCALE HORIZ. 1" = 30.0' VERT. 1" = 20.0'



TYPICAL SECTION OF
SPILLWAY COLLAR ENLARGEMENT



SECTION 40'




CHORD	DISTANCE FROM RIVER WALL SETTING	INVERT ELEV. OF 42" DIA. PIPES	DATE
1	0.0	1976.50	
2	0.5	1976.50	
3	1.0	1976.50	
4	1.5	1976.50	
5	2.0	1976.50	
6	2.5	1976.50	
7	3.0	1976.50	
8	3.5	1976.50	
9	4.0	1976.50	
10	4.5	1976.50	
11	5.0	1976.50	
12	5.5	1976.50	
13	6.0	1976.50	
14	6.5	1976.50	
15	7.0	1976.50	
16	7.5	1976.50	
17	8.0	1976.50	
18	8.5	1976.50	
19	9.0	1976.50	
20	9.5	1976.50	
21	10.0	1976.50	
22	10.5	1976.50	
23	11.0	1976.50	
24	11.5	1976.50	
25	12.0	1976.50	
26	12.5	1976.50	
27	13.0	1976.50	
28	13.5	1976.50	
29	14.0	1976.50	
30	14.5	1976.50	
31	15.0	1976.50	
32	15.5	1976.50	
33	16.0	1976.50	
34	16.5	1976.50	
35	17.0	1976.50	
36	17.5	1976.50	
37	18.0	1976.50	
38	18.5	1976.50	
39	19.0	1976.50	
40	19.5	1976.50	
41	20.0	1976.50	
42	20.5	1976.50	
43	21.0	1976.50	
44	21.5	1976.50	
45	22.0	1976.50	
46	22.5	1976.50	
47	23.0	1976.50	
48	23.5	1976.50	
49	24.0	1976.50	
50	24.5	1976.50	
51	25.0	1976.50	
52	25.5	1976.50	
53	26.0	1976.50	
54	26.5	1976.50	
55	27.0	1976.50	
56	27.5	1976.50	
57	28.0	1976.50	
58	28.5	1976.50	
59	29.0	1976.50	
60	29.5	1976.50	
61	30.0	1976.50	
62	30.5	1976.50	
63	31.0	1976.50	
64	31.5	1976.50	
65	32.0	1976.50	
66	32.5	1976.50	
67	33.0	1976.50	
68	33.5	1976.50	
69	34.0	1976.50	
70	34.5	1976.50	
71	35.0	1976.50	
72	35.5	1976.50	
73	36.0	1976.50	
74	36.5	1976.50	
75	37.0	1976.50	
76	37.5	1976.50	
77	38.0	1976.50	
78	38.5	1976.50	
79	39.0	1976.50	
80	39.5	1976.50	
81	40.0	1976.50	
82	40.5	1976.50	
83	41.0	1976.50	
84	41.5	1976.50	
85	42.0	1976.50	
86	42.5	1976.50	
87	43.0	1976.50	
88	43.5	1976.50	
89	44.0	1976.50	
90	44.5	1976.50	
91	45.0	1976.50	
92	45.5	1976.50	
93	46.0	1976.50	
94	46.5	1976.50	
95	47.0	1976.50	
96	47.5	1976.50	
97	48.0	1976.50	
98	48.5	1976.50	
99	49.0	1976.50	
100	49.5	1976.50	
101	50.0	1976.50	
102	50.5	1976.50	
103	51.0	1976.50	
104	51.5	1976.50	
105	52.0	1976.50	
106	52.5	1976.50	
107	53.0	1976.50	
108	53.5	1976.50	
109	54.0	1976.50	
110	54.5	1976.50	
111	55.0	1976.50	
112	55.5	1976.50	
113	56.0	1976.50	
114	56.5	1976.50	
115	57.0	1976.50	
116	57.5	1976.50	
117	58.0	1976.50	
118	58.5	1976.50	
119	59.0	1976.50	
120	59.5	1976.50	
121	60.0	1976.50	
122	60.5	1976.50	
123	61.0	1976.50	
124	61.5	1976.50	
125	62.0	1976.50	
126	62.5	1976.50	
127	63.0	1976.50	
128	63.5	1976.50	
129	64.0	1976.50	
130	64.5	1976.50	
131	65.0	1976.50	
132	65.5	1976.50	
133	66.0	1976.50	
134	66.5	1976.50	
135	67.0	1976.50	
136	67.5	1976.50	
137	68.0	1976.50	
138	68.5	1976.50	
139	69.0	1976.50	
140	69.5	1976.50	
141	70.0	1976.50	
142	70.5	1976.50	
143	71.0	1976.50	
144	71.5	1976.50	
145	72.0	1976.50	
146	72.5	1976.50	
147	73.0	1976.50	
148	73.5	1976.50	
149	74.0	1976.50	
150	74.5	1976.50	
151	75.0	1976.50	
152	75.5	1976.50	
153	76.0	1976.50	
154	76.5	1976.50	
155	77.0	1976.50	
156	77.5	1976.50	
157	78.0	1976.50	
158	78.5	1976.50	
159	79.0	1976.50	
160	79.5	1976.50	
161	80.0	1976.50	
162	80.5	1976.50	
163	81.0	1976.50	
164	81.5	1976.50	
165	82.0	1976.50	
166	82.5	1976.50	
167	83.0	1976.50	
168	83.5	1976.50	
169	84.0	1976.50	
170	84.5	1976.50	
171	85.0	1976.50	
172	85.5	1976.50	
173	86.0	1976.50	
174	86.5	1976.50	
175	87.0	1976.50	
176	87.5	1976.50	
177	88.0	1976.50	
178	88.5	1976.50	
179	89.0	1976.50	
180	89.5	1976.50	
181	90.0	1976.50	
182	90.5	1976.50	
183	91.0	1976.50	
184	91.5	1976.50	
185	92.0	1976.50	
186	92.5	1976.50	
187	93.0	1976.50	
188	93.5	1976.50	
189	94.0	1976.50	
190	94.5	1976.50	
191	95.0	1976.50	
192	95.5	1976.50	
193	96.0	1976.50	
194	96.5	1976.50	
195	97.0	1976.50	
196	97.5	1976.50	
197	98.0	1976.50	
198	98.5	1976.50	
199	99.0	1976.50	
200	99.5	1976.50	
201	100.0	1976.50	
202	100.5	1976.50	
203	101.0	1976.50	
204	101.5	1976.50	
205	102.0	1976.50	
206	102.5	1976.50	
207	103.0	1976.50	
208	103.5	1976.50	
209	104.0	1976.50	
210	104.5	1976.50	
211	105.0	1976.50	
212	105.5	1976.50	
213	106.0	1976.50	
214	106.5	1976.50	
215	107.0	1976.50	
216	107.5	1976.50	
217	108.0	1976.50	
218	108.5	1976.50	
219	109.0	1976.50	
220	109.5	1976.50	
221	110.0	1976.50	
222	110.5	1976.50	
223	111.0	1976.50	
224	111.5	1976.50	
225	112.0	1976.50	
226	112.5	1976.50	
227	113.0	1976.50	
228	113.5	1976.50	
229	114.0	1976.50	
230	114.5	1976.50	
231	115.0	1976.50	
232	115.5	1976.50	
233	116.0	1976.50	
234	116.5	1976.50	
235	117.0	1976.50	
236	117.5	1976.50	
237	118.0	1976.50	
238	118.5	1976.50	
239	119.0	1976.50	
240	119.5	1976.50	
241	120.0	1976.50	
242	120.5	1976.50	
243	121.0	1976.50	
244	121.5	1976.50	
245	122.0	1976.50	
246	122.5	1976.50	
247	123.0	1976.50	
248	123.5	1976.50	
249	124.0	1976.50	
250	124.5	1976.50	
251	125.0	1976.50	
252	125.5	1976.50	
253	126.0	1976.50	
254	126.5	1976.50	
255	127.0	1976.50	
256	127.5	1976.50	
257	128.0	1976.50	
258	128.5	1976.50	
259	129.0	1976.50	
260	129.5	1976.50	
261	130.0	1976.50	
262	130.5	1976.50	
263	131.0	1976.50	
264	131.5	1976.50	
265	132.0	1976.50	
266	132.5	1976.50	
267	133.0	1976.50	
268	133.5	1976.50	
269	134.0	1976.50	
270	134.5	1976.50	
271	135.0	1976.50	
272	135.5	1976.50	
273	136.0	1976.50	
274	136.5	1976.50	
275	137.0	1976.50	
276	137.5	1976.50	
277	138.0	1976.50	
278	138.5	1976.50	
279	139.0	1976.50	
280	139.5	1976.50	
281	140.0	1976.50	
282	140.5	1976.50	
283	141.0	1976.50	
284	141.5	1976.50	
285	142.0	1976.50	
286	142.5	1976.50	
287	143.0	1976.50	
288	143.5	1976.50	
289	144.0	1976.50	
290	144.5	1976.50	
291	145.0	1976.50	
292	145.5	1976.50	
293	146.0	1976.50	
294	146.5	1976.50	
295	147.0	1976.50	
296	147.5	1976.50	
297	148.0	1976.50	
298	148.5	1976.50	
299	149.0	1976.50	
300	149.5	1976.50	
301	150.0	1976.50	
302	150.5	1976.50	
303	151.0	1976.50	
304	151.5	1976.50	
305	152.0	1976.50	
306	152.5	1976.50	
307	153.0	1976.50	
308	153.5	1976.50	
309	154.0	1976.50	
310	154.5	1976.50	
311	155.0	1976.50	
312	155.5	1976.50	
313	156.0	1976.50	
314	156.5	1976.50	
315	157.0	1976.50	
316	157.5	1976.50	
317	158.0	1976.50	
318	158.5	1976.50	
319</			

APPENDIX II
PHOTOGRAPHS


47



TOP OF EARTHEN BERM
VIEW FROM NORTHEAST
Photo #1




PRINCIPAL SPILLWAY STRUCTURE
(GOOD CONDITION)
Photo #2



STILLING BASIN AND OUTLET PIPE
(NOTE RIP RAP AND STILL WATER SURFACE)
Photo #3



DOWNSTREAM CHANNEL
(GOOD CONDITION)
Photo #4



EMERGENCY SPILLWAY
(NOTE CUT IN BACKGROUND)
Photo #5



LOWER END EMERGENCY SPILLWAY
(NOTE BROAD FLAT AREA)
Photo #6

APPENDIX III
FIELD OBSERVATIONS

FIELD OBSERVATIONS

Name of Dam: Upper North River No. 76 (Elkhorn Lake Dam)

County: Augusta

State: Virginia

Coordinates: Lat 38° - 19.6' Long 79° - 13.25'

Date of Inspection: December 13, 1978

Weather: Fair, temperature 45°

Pool Elevation at Time of Inspection: 2015.75 M.S.L.

Tailwater at Time of Inspection: 1966.5 M.S.L.

Inspection Personnel:

Schnabel Engineering Associates, P. C.
Ray E. Martin, P.E.
Stephen G. Werner (recorder)

J. K. Timmons and Associates, Inc.
Robert G. Roop, P.E.
William A. Johns (recorder)

State Water Control Board
John Hyden

1 Embankment:

1.1 Surface Cracks: The slopes, crest, emergency spillway, and abutment contacts were inspected and no cracks were noted. The embankment portion of the dam and spillway were covered with 3 to 4 ft high, light vegetation, making observations difficult. Small (1 to 2" diameter) trees were growing along the embankment at the north abutment contact and also on the downstream slope near the center of the embankment.

1.2 Unusual Movement: No unusual movements were noted on the dam or downstream beyond the embankment toe.

1.3 Sloughing or Erosion: No sloughing was noted, however, minor erosion was noted along the south and north abutment contacts.

The erosion consisted of approximately 6-inch deep gullies.

1.4 Alignment: The vertical and horizontal alignment of the dam was visually observed to be in accordance with "as built" drawings.

1.5 Riprap: Showed no displacement or washing and appeared to be in proper alignment.

1.6 Junctions: Conditions appear good at the junction of the embankment and the abutments. Numerous sandstone outcrops are exposed throughout the steep ridge which forms the north abutment. The sandstone is brown to gray, fine-grained and is thinly to massively bedded. Crossbeds occur locally. Bedrock strikes $65^{\circ}\text{NE}_{\pm}$ and dips $18^{\circ}\text{SE}_{\pm}$. Wedge-shaped or subrectangular joint sets were also measured: N25W, 90 and N85E, 85SE. The emergency spillway is in cut along the south abutment, which includes steep cut slopes (75-100'± high) with benches. Slopes are not vegetated and the spillway is cut primarily in sandstone. Scattered shale interbeds near the middle of the slopes are capped with red shale. Bedrock strikes $65^{\circ}\text{NE}_{\pm}$ and dips $10^{\circ}\text{SE}_{\pm}$.

1.7 Seepage: One damp spot was noted about 20 ft right of the left abutment and about 50 ft downstream of the midslope drainage berm. We believe this wet area at about EL 2005 is the result of surface water seeping from the drainage berm above.

1.8 Staff Gage: None found.

1.9 Drains: The embankment contains a downstream rock toe drain which extends to about EL 2023 along the north abutment and along the toe of the embankment and a portion of the emergency spillway. This elevation along the left abutment corresponds with the outfall elevation of the downstream drainage berm at the left abutment. No discharge outlets were noted, however, the drain terminates on each side of the principal spillway pipe and is presumed to discharge into the downstream channel at this point. The midslope drainage berm contained a few wet spots which coincided with low areas and these are believed to be trapped surface water from rains which occurred just prior to the inspection. The approximate locations of these wet areas are illustrated on Sheet 2 in Appendix I.

2 . Reservoir:

2.1 Slopes: The upstream end of the reservoir is occupied by the river floodplain. Steep natural rock slopes with numerous sandstone outcrops bound the left side of the reservoir. The right side of the reservoir is graded locally but consists primarily of moderate to steep natural rock slopes, with sandstone and shale outcrops. No slide areas were noted around the perimeter of the reservoir. Sloughing was observed along the toe of the cut slope at the east end of the spillway.

2.2 Sedimentation: Slight sedimentation at stream inflow (alluvial fan of rock and sand). No evidence of any bottom sediment buildup. Water was very clear.

3 Downstream Channel:

3.1 Condition: Good. Channel has rock bottom.

3.2 Slopes: Downstream, steep natural slopes with sandstone and shale outcrops occur along the left and right sides of the stream. The stream valley narrows considerably, below the dam. No slope failures were noted in the valley adjacent to the toe of the dam.

3.3 Population and Facilities: None. Staunton Lake is 9,000' downstream.

4 Principal Spillway:

4.1 Intake Structure: The structure was in good condition. Gates were well greased, however, the lower gate is inoperable. Catwalk was in good condition. Concrete on the structure visually was in good condition.

4.2 Outlet Structure: Was in good condition. This was viewed from the downstream end and pictures of this can be seen in Appendix II.

5 Emergency Spillway:

5.1 Channel Section: Was found to be in uniform shape with exception of one section adjacent to Handkney Mountain, which showed sloughing of side slope. The bottom and side adjacent to berm was well vegetated

and found to be in design configuration. The rip side slope was in good condition. The lower end was a broad flat area in uniform design configuration.

6 Instrumentation:

6.1 Monumentation: None

6.2 Observation Wells and Piezometers: No observation wells or piezometers were noted in the field.

1. H. C. Taylor, State Conservation Engineer - 2225, Route 1, 1935
222, Richmond, Virginia

2. Roy H. Baker, Asst. Soil Mechanics Laboratory,
222, Richmond, Virginia

3. Virginia 22-2, Upper North River, site 15, 16

APPENDIX IV

1. Data 22-2, Soil Mechanics Laboratory Data, 1 sheet.
2. Data 22-2, Supplemental and Extension to Appendix Report, 14 sheets.
3. Figures 1 and 2, Volume 1, Soil Mechanics Laboratory, 14 sheets.
4. Data 22-2, Supplemental and Extension to Appendix Report, 14 sheets.
5. Data 22-2, Figure 3, Analysis of Large Diameter River Spectra,
1 sheet.
6. Data 22-2, Figure 4, Summary of Soil Engineering Properties as Determined
by Laboratory Tests, 1 sheet.
7. Data 22-2, Figure 5, Summary of Soil Engineering Properties as Determined
by Field Tests, 1 sheet.
8. Figure 6, Summary of Soil Engineering Properties as Determined by
Field Tests, 1 sheet.
9. Figure 7, Summary of Soil Engineering Properties as Determined by
Field Tests, 1 sheet.
10. Figure 8, Summary of Soil Engineering Properties as Determined by
Field Tests, 1 sheet.
11. Figure 9, Summary of Soil Engineering Properties as Determined by
Field Tests, 1 sheet.
12. Figure 10, Summary of Soil Engineering Properties as Determined by
Field Tests, 1 sheet.
13. Geological Map and Profile

APPENDIX IV

STABILITY ANALYSIS

TO : R. C. Barnes, State Conservation Engineer, DATE: June 8, 1962
SCS, Richmond, Virginia

FROM : Ray S. Decker, Head, Soil Mechanics Laboratory,
SCS, Lincoln, Nebraska

SUBJECT: Virginia FP-2, Upper North River, Site No. 76

ATTACHMENTS

1. Form SCS 354, Soil Mechanics Laboratory Data, 4 sheets.
2. Form SCS 352, Compaction and Penetration Resistance Report, 15 sheets.
3. Figures 1 and 2, Void-Ratio and Percent Consolidation vs. Load Curves, 2 sheets.
4. Form SCS 355, Triaxial Shear Test Data, 6 sheets.
5. Form SCS 353, Figure 3, Gradation of Large Diameter Shear Specimens, 1 sheet.
6. Form SCS 347, Figure 4, Summary of Soil Engineering Properties on South Fork Watershed, West Virginia, 1 sheet.
7. Form SCS 357, Summary - Slope Stability Analysis, 3 sheets.
8. Figure 5, Estimate of Construction Pore Pressure, 1 sheet.
9. Figure 6, Estimate of Seepage through the Bedrock in the Flood Plain Section, 1 sheet.
10. Form SCS 353, Figure 7, Grain Size Distribution Graph, 1 sheet.
11. Figure 8, Percent Consolidation vs. Load for the Embankment Core, 1 sheet.
12. Form SCS 372, Embankment Placement Recommendations, 2 sheets.
13. Geological Plans and Profiles.

DISCUSSION

FOUNDATION:

- A. Classification: The bedrock at this site consists of alternating beds or stratum of very fine sandstone and siltstone or mudstone. The bedrock in the valley is described as extremely hard.

Bedrock is exposed on the relatively steep left abutment and in the channel section. The bedrock in the flood plain and terrace level to the right of the channel is mantled with gravelly and cobbly material. The thickness of the mantle through these sections ranges from about 8 feet to 40 feet. Samples of the mantle from the vicinity of the toe drain indicate that the material in the flood plain is very coarse (27% finer than No. 4); whereas, the surface material in the terrace is considerably finer with about 55% finer than the No. 4 size and 8% cobbles.

The bedrock in the right abutment is mantled with residual silty sands to depths of about 20 feet.

- B. Shear Strength: Standard penetration tests were made in the alluvial and colluvial gravels. The blow count was high; it is questionable, however, whether blow count can be related to shear strength in a cobbly material.

such as this. A triaxial shear test was made on material from the flood plain borrow area. The shear data obtained is discussed under the embankment section of this report. Based on the shear tests made, it appears that $\phi = 35^\circ$ would be a conservative design value for the gravelly and cobbly foundation material.

- C. Permeability: Field permeability tests were made in two locations in the terrace material. Computed permeability rates based on the field permeability test data in the geologic report are in the range of 3 to 5 feet per day in the tighter material and from 37 to 36 feet per day in the somewhat looser (lower blow count zone) material. The computed rates for each field test are shown on the attached profile. The rates were computed from the equation and data given in the open end permeability test procedure in the Bureau of Reclamation's, "Earth Manual". There is a small error involved since the head was not constant. The rates were computed to show ranges of permeability and are believed to be satisfactory for this purpose.

Pressure tests were conducted in the bedrock at several locations. The results of the tests are included in the geology report. Permeability rates were computed from this data in accordance with the equation $k = C_p \frac{Q}{H}$.

given in the Packer test procedure in the Bureau of Reclamation's "Earth Manual". H was considered as the distance from the ground surface to the midpoint of the test zone. No water table was considered, except in test hole # 2 where the water table was considered at 22.5 feet. The diameter of the test hole was considered as NX.

The computed permeability rates are shown on the attached Form SCS 35D.

EMBANKMENT:

- A. Classification: The borrow materials fall into two general categories consisting of (1) weathered sandstone and siltstone from the emergency spillway and the abutment downstream from the spillway and (2) the flood plain material.

Samples of the weathered sandstone ranged from CL-ML to GC-GM. The general range of material appears SC-SM, however, with the percent of fines ranging 23 on the GC-GM to 53 on the CL-ML. The percent of gravel ranged from 15 to 45 percent.

The flood plain gravels can be divided into two general groups, based on the amount of gravel or cobbles larger than 3.0 inches. Samples 62F1108, 62F1109, 62F1110 and 62F1112 contained from 24 to 36 percent material finer than 3.0 inches in diameter. Samples 62F1111, 62F1113 and 62F1114 contain from 53 to 63 percent finer than 3.0 inches in diameter.

- B. Permeability: Estimated permeability rates of the embankment materials are shown in the following table:

3 - R. C. Lamm - 6/2/62

Ray S. Becker

Subj: Virginia FP-2, Upper North River, Site No. 76

Type of Material	Lab. Sample No.	k Ft./Day	Size Range Considered
Residual Silty Sandstone	62F11097	0.007	Minus No. 4
(Imbankment Core)	62F11103	0.009	Minus No. 4
Coarse Flood Plain Borrow	62F11108	18.0	Field Gradation Fraction Finer Than 6.0"
(Shell Section)		0.03	
	62F11109	200+	Field Gradation Fraction Finer Than 6.0"
		25.0	
	62F11110	180	Field Gradation Fraction Finer Than 6.0"
		17.0	
	62F11112	200+	Field Gradation Fraction Finer Than 6.0"
		3.0	
Finer Flood	62F11111	6.0	Fraction Finer Than 6.0"
Plain and Terrace	62F11113	0.5	Fraction Finer Than 6.0"
Borrow	62F11114	1.5	Fraction Finer Than 6.0"
(Shell Section)			

The permeability rates shown for the core section were measured rates on the consolidation test specimens. The rates shown for the shell materials were estimated from Hazen's Formula, $k = 2 (D_{10})^2$, where the D_{10} size is in mm. and k is in feet/minute. The computed rates are reported in feet/day and were reduced one order of magnitude, according to the approximate correlation of D_{10} to D_5 size as contained in the preliminary report by Moran, Proctor, Mueser and Rutledge on the "Study of Effective Use of Coarse Grained Soils in Construction of Earth Fill Dams".

- C. Compacted Density: Standard Proctor compaction tests were made on the minus No. 4 size fraction on 15 of the borrow samples submitted. The test data is shown on the attached Forms SCS 352. Corrected density for material larger than No. 4 size is also shown.

The borrow samples were submitted in moisture-proof bags. In order to obtain additional information on the compaction characteristics as well as the field moisture content, a small portion of the moist sample finer than 1 1/2 inches in diameter was compacted in a 1/30 cubic foot mold and also in a 1/13.3 cubic foot mold using Standard Proctor effort. The 1/30 cubic foot mold has a 4.0" diameter and the 1/13.3 cubic foot mold has a 6.0 inch diameter.

R. C. Barnes -- 9/5/62

Ray S. Becker

Subj: Virginia PP-2, Upper North River, Site No. 76

After compaction in this manner, the gradation was determined from the material in the 1/30 cubic foot mold. With percent of material larger than No. 4 known, it was then possible to compute the density and moisture content of the minus No. 4 fraction.

The Standard USER equations for correcting the compacted density and moisture content based on the percent material larger than No. 4 size were used. The density and moisture content of the soil and rock mixture ^{was} known. Therefore, the equations were solved for the density and the moisture content of the minus No. 4 fraction. The computed density and moisture content of the minus No. 4 fraction is shown on the compaction reports with relation to the Standard compaction curve.

You will note that there is pretty good agreement between the Standard Proctor curve and the computed densities. It is, therefore, considered that the "rock correction" as normally used by the Laboratory is reasonable for density control of these materials.

- 62F1097
- D. Consolidation: Consolidation tests were made on two samples that represent the core section of the embankment. The tests were made on the minus No. 4 fraction from Samples 62F1107 and 62F1103. The test samples were compacted to 95 percent of Standard Proctor density. The void-ratio versus load and the percent consolidation of the Laboratory samples are attached, Figures 1 and 2.
- E. Shear Strength: Triaxial shear tests were made on Samples 62F1097, 62F1103 and 62F1107 to represent the center section of the embankment. Shear tests were made on a mixture of 62F1103, 62F1111, 62F1113 and 62F1114 to represent the shell sections. A total of three tests were made on this material, consisting of two tests using 4.0 inch diameter test specimens with a maximum particle diameter of 1.0 inch and one test using 6.0 inch diameter test specimens with a maximum particle diameter of 1 1/2 inch. The shear data obtained are summarized as follows:

Sample No.	Emb. Sec. Represented	Diameter of Test Specimen (Inches)	Density (p.c.f.)	% of Standard Proctor	Degree of Saturation (%)	ϕ	c (p.s.f.)
62F1097	Center	1.4	105.5	95.4	98+	23.5°	500
62F1103	Center	1.4	103.6	94.8	95+	23°	350
62F1107	Center	1.4	110.5	95.2	97+	26°	350
62F1108	Shell	4.0	127	95	82-88	36°	0
1111	Shell	4.0	132.5	100	91-97	35°	575
1113	Shell	6.0	138.5	102	100	43°	1000
1114							

Pore pressure was measured during the test on Sample 62F1103 and the effective stress values are recorded on the triaxial shear test data sheet.

Ray S. Decker

Subj: Virginia PP-2, Upper North River, Site No. 76

The gradation used for tests on the shell material is shown on the attached Form SCS 353, Figure 1. The test samples were regraded as shown. Some trouble was encountered with consolidation and glycerine leaks on those large diameter test specimens. The data is believed to be quite consistent, however, in that the strength increased with density as would be expected. The c value obtained is believed to be due primarily to the increased density of the fines. You will note that c was 0 at 95% of Standard, 575 p.s.f. at 100% of Standard and 1000 p.s.f. at 102% of Standard Proctor. The increase in ϕ between the 4.0 inch diameter tests and the 6.0 inch diameter test is due, in part, to the increase in gravel percentage from 44 to 56%, respectively.

The shear data obtained on these gravelly materials are in pretty good agreement with data previously obtained on granular material from the South Fork Watershed in West Virginia. A summary of the average values from the South Fork Watershed is attached for comparison, Figure 4.

SLOPE STABILITY:

The stability of the proposed embankment was checked with a Modified Swedish Circle Method of analysis. Two sections were analyzed -- one at the channel section where the bedrock occurs at a very shallow depth and one on the terrace section where from 30 to 40 feet of gravelly material overlies bedrock.

The analysis considered a zoned embankment with a phreatic line from emergency spillway elevation (2064) to a drain at $c/b = 0.6$. The shear strength of Sample 62F1097 ($\phi = 23.5^\circ$, $c = 500$ p.s.f.) from the emergency spillway was used to represent the core. The shell material was considered to be represented by Samples 62F1108, 62F1111, 62F1113 and 62F1114. The shell was considered at 100% of Standard Proctor with shear strength of $\phi = 36^\circ$, $c = 575$ p.s.f. At the maximum section the analysis considered the embankment only. Satisfactory factors of safety (greater than 1.5) were obtained on a 2 1/2:1 upstream slope when the central core was limited to 3/4:1 (Trial No. 1 and Trial No. 1A). Trial No. 1B shows that a 3:1 slope is required to obtain a factor of safety of 1.50 on the upstream slope when the upstream slope of the central core is 1 1/2:1.

The analysis showed a factor of safety of 1.82 for a 2 1/2:1 downstream slope with the slope of the central core at 1 1/2:1. This factor of safety would be increased somewhat if the shell section, with selective placement, effectively drains the central core.

The analysis on terrace section assumed that the shear strength of the gravelly foundation was $\phi = 36^\circ$, $c = 0$. The central core and the shell were considered the same as at the maximum section. This analysis shows that the proposed 2 1/2:1 upstream slope requires modification to obtain a factor of safety of 1.50. This could be accomplished by wide stabilizing berms as shown by Trial Circles 4A and 5A or by flattening the upstream slope to 3:1 (Trial Circle No. 6). The analysis at this embankment section considered a slope of 3/4:1 on the central core. A flatter slope such as 1:1 or 1 1/2:1 could be used, however, with very little change in the factor of safety, since the trial failure arc was restricted to the central core.

Ray S. Decker

Subj: Virginia HP-2, Upper North River, Site No. 76

A 3:1 upstream slope was checked for safety against overtopping with an infinite slope analysis. For this purpose, shear strength of $\phi = 36^\circ$, $c = 0$ was used. A factor of safety of 1.15 was obtained when horizontal seepage forces were considered. The factor of safety obtained is considered adequate.

The water forces considered in this analysis are more severe than will result from construction pore pressure if the center section material is placed with a moisture content less than 3 to 4 percent wet of optimum. The construction pore pressure was estimated according to Hilt's Method based on the laboratory consolidation curves. A plot of the construction pore pressure versus total stress is attached (Figure 5). The plot shows construction pore pressure for placement moisture contents of 17 percent, 19 percent and 21 percent, which covers the range from about optimum to 4 percent over optimum.

Trial Circle No. 7 on the attached slope stability summary shows the factor of safety obtained ($F_s = 2.2$) when estimated construction pore pressure was based on a placement moisture content of 21 percent.

RECOMMENDATIONS

- A. Site Preparation: Any overhangs or loose talus material that may be present should be removed from the relatively steep left abutment.
- B. Centerline Cutoff: We recommend a cutoff to bedrock at this site. This will involve relatively deep excavation through the moderate to highly permeable terrace gravels.

A minimum trench bottom width of 30 feet is recommended for the flood plain section and a minimum trench bottom width of 20 feet is recommended through the terrace section. Normal foundation preparation will probably remove most of the material overlying bedrock in the channel section; if not, the trench bottom width should be about 30 feet.

The formula $w = h - d$ taken from the Bureau of Reclamation's, "Design of Small Dams", was used as a basis for the suggested trench bottom widths. The reservoir head (h) was considered from normal pool level.

Based on the pressure tests made, it is apparent that seepage may be expected through the bedrock. In order to get some idea of the amount of seepage, the conditions shown on the attached Figure 6 were assumed. The estimated seepage loss through the flood plain section is 0.05 c.f.s. with the conditions assumed. Considering losses through the abutments, this figure may double. This estimate is conservative if the permeability of the bedrock is in the range of 2.5 ft./day or less.

The cutoff trench should be backfilled with SC or CL material and compacted to a minimum of 95 percent of Standard Proctor with the moisture content controlled to near optimum.

C. Principal Spillway: We recommend that the principal spillway be placed on bedrock. It appears that the amount of trench excavation could be reduced by shifting the conduit to the left of the proposed location shown on the attached Form SCS 350.

D. Drain: Drainage is required for embankment stability and also to provide a safe outlet for seepage that by passes the cutoff trench through the bedrock. We recommend selective placement of the flood plain borrow in the downstream shell to control the phreatic line in the embankment. This may be accomplished by placing the coarse flood plain material in the outer shell of the downstream section with a transition zone of the finer flood plain material like Samples 62F1113 and 62F1114 between the core and the outer shell. The suggested placement for drainage purposes is shown on the attached Form SCS 372. The relation of the gradation of each of the embankment zones and the foundation material is shown on the attached Form SCS 353, Figure 7.

In addition to selective placement of the embankment, we recommend a rock toe drain to provide a safe outlet for seepage through the bedrock. The toe drain should bottom on bedrock through the flood plain and penetrate the terrace material to about an 8.0 foot depth. The coarse flood plain material like Sample 62F1109 should be used as a transition filter between the foundation and the rock toe.

A D₁₅ size of about 3 inches is suggested for the rock toe drain.

E. Settlement: The estimated settlement of the central core is 2 percent or 2 feet at the maximum section. The consolidation tests of the minus No. 4 fraction ~~2%~~ used as a basis for this estimate. The percent consolidation versus load obtained on laboratory tests was reduced in proportion to the percentage of material larger than the No. 4 size. An average of 30% gravel was considered. The corrected consolidation curve is shown on the attached Figure 8.

F. Selection of Material: A zoned fill is recommended. Suggested placement of material, minimum density and placement moisture ranges are shown on the attached Form SCS 372. The minimum placement density suggested for the minus No. 4 fraction is 95% of Standard Proctor for the core and 100% of Standard Proctor for the shell.

G. Slopes: The results of the stability analysis are summarized as follows:

Section	Slope of the Outside Shell		Slope of the Core		F _s	Beam Width
	Upstream	Downstream	Upstream	Downstream		
Maximum at Station 21+25	2 1/2:1		1 1/2:1		1.35	10'
		2 1/2:1		1 1/2:1	1.82	Normal 10'
	2 1/2:1		3/4:1		1.63	10'
	3:1		1 1/2:1		1.55	10'
Terrace Section at Station 19+50	2 1/2:1		3/4:1		1.33	10'
	2 1/2:1		3/4:1		1.50	55'
	3:1		3/4:1		1.50	10'

Ray S. Decker

Subj: Virginia PP-2, Upper North River, Site No. 76

We suggest embankment slopes of 3:1 upstream and $2\frac{1}{2}$:1 downstream with the 10 foot berms as originally proposed. The slope of the central core can be as flat as $1\frac{1}{2}$:1, depending on availability of material.

Prepared by:

Lorn P. Dennigan

Reviewed and Approved by:

Roland B. Phillips

Attachments

cc: R. C. Barnes (6 Four are being forwarded now and two the first of next week)
H. M. Keuts, Upper Darby, Pennsylvania (2)
G. W. Gruth, Upper Darby, Pennsylvania

SUMMARY - SLOPE STABILITY ANALYSIS

Sheet 1 of 3

State MISSISSIPPI Project USDA Flood Plain Study

Date 5-16-62 Analysis Made By TECHNICAL Checked By C.E.F.


Method of Analysis SWEDISH METHOD

Location of Material	Date				State			
	Emb.		Emb.		Emb.		Emb.	
	95% sat		95% sat		95% sat		95% sat	
	50		50		50		50	
Sample No.	125 1097		125 1100		125 1107		125 1114	
γ_d	113.0		103.5		116.5		122.5	
γ_m	130.0		121.5		125.5		144.5	
γ_s	133.0		126.0		121.5		146.0	
γ_b	70.5							
Condition	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.
ϕ				23.5°	$\phi' = 31.5$	(FROM TEST DATA SHEET - 02m)		
Tan ϕ				0.435	0.532		0.455	0.777
K								
C				500	C' = 350	(")	250	505

UPSTREAM SLOPE			
Trial	Slope	Conditions	Fs
#1	2 1/2:1	Full drawdown - 10' berm @ elev 2015.5'- Ave cut from top shoulder thru second emb. with 3/4:1 slope on core. Sat. shear values only.	1.63
#1A	2 1/2:1	Same as No. 1 but with 1 1/2:1 slope on core	1.35
#2	2 1/2:1	Full drawdown - 10' berm @ elev 2015.5'- Ave cut from top shoulder thru second emb. with 3/4:1 slope on core. Sat. shear values only.	1.73
#2A	2 1/2:1	Same as No. 2 but with 1 1/2:1 slope on core	1.44
#1B	3:1	Same as No. 1A but with 3:1 slope on shell	1.55

DOWNSTREAM SLOPE			
Trial	Slope	Conditions	Fs
#3	2 1/2:1	Drain @ 9/16" dia - 10.0' berm @ elev 2026.0'- Ave cut from top shoulder thru second emb. with 1 1/2:1 slope on core. Sat. shear values only.	1.52
#7	2 1/2:1	Factor of Safety Against Construction Failure - Estimated Pore Pressure Based on Placement Moisture Content of 21% Note: Third Emb.; Shell of 62F 1105, 1114 Core of 62F 1097	2.2

To be used to report to field offices data used for slope stability analyses and the results of the analyses. The right side of the form will be used for a sketch of the embankment on which the analyses have been made.



Maximum Section

Sta. 21+25

Scale 1 inch = 10 Feet

SUMMARY - SLOPE STABILITY ANALYSIS

Sheet 2 of 3

State VIRGINIA Project UPPER NORTH RIVER SITE # 76

Date 6-1-62 Analysis Made By GLM Checked By G.N.G

Method of Analysis SWEDISH CIRCLE


To be used to report to field offices data used for slope stability analyses and the results of the analyses.
The right side of the form will be used for a sketch of the embankment on which the analyses have been made.

Location of Material	<u>Found</u>				<u>Emb</u> <u>95% Std</u> SC		<u>Emb</u> <u>100% Std</u>			
Sample No.	Assumed				62F1097		1108, 1111, 62F1113, 1114			
γ_d					113.0		132.5			
γ_m					130.0		144.5			
γ_s	146.0				133.0		146.0			
γ_b					70.5		83.5			
Condition	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.
ϕ		36°				23.5°		36°		
Tan ϕ		0.727				0.435		0.727		
K										
C		0				500		575		

UPSTREAM SLOPE			
Trial	Slope	Conditions	Fs
4	2 1/2:1	Full drawdown; 10' berm @ el. 2015.5; Arc cut from app shoulder thru zoned emb & 24' into found.	1.33
4A	2 1/2:1	Same as #4 except with 55' berm @ el. 2015.5.	1.50
5	2 1/2:1	Full drawdown; 10' berm @ el. 2015.5; Arc cut from app shoulder thru zoned emb & 35' into found.	1.43
5A	2 1/2:1	Same as #5 except with 10' berm @ el. 2015.5.	1.50

DOWNSTREAM SLOPE			
Trial	Slope	Conditions	Fs
NOTE:			
Sat. shear values on all trials			
Zoned emb:			
Core - 23.5° - 500			
Shell - 36° - 575			

Flood Plain Section
Station 19+50



SUMMARY - SLOPE STABILITY ANALYSIS

State VIRGINIA Project UPPER NORTH RIVER SITE # 76

Date 6-4-62 Analysis Made By GLM Checked By G.N. G.


Method of Analysis SWEDISH CIRCLE

To be used to report to field offices data used for slope stability analyses and the results of the analyses. The right side of the form will be used for a sketch of the embankment on which the analyses have been made.

Location of Material	Found				Emb 95% Std SC		Emb 100% Std			
Sample No.	Assumed				62F1097		62F ^{1108, 1111} 1113, 1114			
τ_d					113.0		132.5			
τ_m					130.0		144.5			
τ_s	146.0				133.0		146.0			
τ_b					70.5		83.5			
Condition	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.
ϕ		36°				23.5°		36°		
Tan ϕ		0.727				0.435		0.727		
K										
C		0				500		575		

UPSTREAM SLOPE-			
Trial	Slope	Conditions	Fs
6	3:1	Full drawdown; 10' berm @ el. 2215.5; Arc cut from opp shoulder thru zoned emb & 28' into found. Sat shear values only.	1.50
		Note: Zoned Emb.	
		Shell - 36° - 575	
		Core - 23.5° - 500	

[illegible]



RECOMMENDED USE OF EXCAVATED MATERIAL

☐ Formal Zoning Plan ☒ Selective Placement Plan

state VIRGINIA

State of UPPER NORTH RIVER

te 6-5-62

007-18

Emergency Spillway Crest E1.

Elevation

202

Section


TYPICAL EMBANKMENT SECTION

Sec. No.	Embankment Section	Source of Fill Material					Lab. Sample No.	Lab Test	Lab. Curve No.	Compaction Requirements Class of Fill <i>B-2</i>		
		Description	Location	Ave. Depth		Minimum Density				Moisture Range		
				From	To							
											Lbs. per Cu. Ft.	Percent
							Max. Den.	Optm. Moist.		From	To	
1	Cut-off Trench & Core	Emer Spwy.		1	12	1097	111.0	17	3	105.0	16.0	19.0
	"	"		1	12	1098	113.0	16.5	4	107.0	15.0	18.0
	"	"		1	12	1099	105.5	19.5	5	100.5	18.0	21.5
	"	"		1	12	1100	112.0	16.0	6	106.0	14.0	17.5
	"	"		1	12	1101	113.5	15.0	7	108.0	14.0	17.0
	"	"	Borrow Area	1	12	1103	109.5	17.0	9	104.0	16.0	19.0
	"	"	"	1	12	1164	109.6	17.0	10	104.0	15.0	19.0
	"	"	"	1	12	1105	115.6	14.5	11	109.0	13.0	16.0
	"	"	"	1	12	1167	116.0	13.5	13	110.0	12.0	15.0
		Densities Shown are For The	Minus No	4	Fraction							

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

RECOMMENDED USE OF EXCAVATED MATERIAL
☐ Formal Zoning Plan ☐ Selective Placement Plan

state VIRGINIA
Project UPPER NORTH RIVER #1
Date 6-7-62
By LPD



TYPICAL EMBANKMENT SECTION

Sec. No.	Embankment Section	Description	Source of Fill Material				Lab. Sample No.	Lab Test	Lab. Curve No.	Compaction Requirements Class of Fill G-1		
			Location	Ave. Depth		Minimum Density				Moisture Range		
				From	To							
											Max. Den.	Optm. Moist.
2014	Transition or Upstream -	Flood Plain & Terrace	1	7	62 F	1235	12.0	19	123.5			
	"	"	1	6		1260	9.5	20	126.0			
3	Downstream - Outer shell -	Flood Plain	1	7	1109				111.5			
	"	"	1	6	1110				111.5			
	"	"	1	4	1112	111.5	13.5	18	111.5			
4	Upstream shell	Flood Plain	1	7	1111	1180	12.0	17	118.5			
	"	Flood Plain	1	7	1108	1170	13.0	13	117.0			
	"	Alluvial & Colluvial	1	12	1102	113.5	14.5	8	113.5			
		Densities Shown are			For the	Minus 4			Fraction			

R. C. Barnes, State Conservation Engineer,
SCS, Richmond, Virginia

August 22, 1962

Ray S. Decker, Head, Soil Mechanics Laboratory,
SCS, Lincoln, Nebraska

Virginia FPP - Upper North River, Site No. 76

We have reviewed placement recommendations for coarse materials on the subject site, as requested by telephone call from Mr. Oman.

Original shear tests on coarse material for this site were run on a composite of Samples 62F1108, 1111, 1113 and 1114 as representing flood plain material with the most fines.

Test densities for shear tests were based upon assumption that all material 6 inches and over would be raked from the mass of the fill to the outside shells. With this assumption, the composite would have about 47% larger than #4 with an average density on - #4 of 119 p.c.f.

The shear tests were run on material finer than 1 inch. The test specimens were re-graded in the sand and gravel size range as shown in the original report. There was 44 percent plus No. 4 material in the 4.0 inch diameter test specimens and 56 percent plus No. 4 material in the 6.0 inch shear specimens.

With the minus No. 4 material at 95% of Standard Proctor (113 p.c.f.), the corrected density with 44 percent gravel included in the sample would be 128 p.c.f. With the minus No. 4 material at 100% of Standard Proctor, the corrected density with 44 percent gravel in the sample would be 132 p.c.f.

The 6.0 inch diameter test specimens contained 56 percent gravel. Maximum Standard density, considering this percentage of gravel, would be 137 p.c.f.

The first shear tests were set up at about 127 p.c.f. which would represent about 95% of the Standard Proctor density for the gradation used. These specimens slumped before testing and it was deemed necessary to test at higher densities. The second and third tests were run at densities of 132 p.c.f. and 138.5 p.c.f. which would represent about 100% of Standard Proctor density for the gradation used.

Strength values used in the stability analyses were for $\gamma_d = 132$ p.c.f.

After reviewing the data on gradation of field samples which show that the above composite would have about 70% larger than No. 4 and about 30% larger

2 -- R. C. Barnes -- 8/22/62

Ray S. Decker

Subj: Virginia FPP - Upper North River, Site No. 76

than 6", we concur in the idea that removing all 6" and larger material would not be practical.

Since our report of June 8, 1962 on this site, we have had opportunity to review the Rutledge report on coarser material. Data in that report based upon U.S.B.R. tests on - 3" material show that material tested at 125 p.c.f. on the - 3" fraction gave ϕ values of 33° to 42° .

We have re-analyzed the designs proposed in our report of June 8 using upstream slopes of 3:1 for the outside shell and $3/4:1$ for the interior core with berm at 2015.5 and embankment values of $\gamma_d = 125$ p.c.f., $\phi = 38^\circ$, $c = 0$. This analysis produced $f_s = 1.52$. (Trial circle 1C on the attached slope stability summary.)

Further review of the volumes of borrow material show that Samples 62F1111 and 1114 represent some 240,000 cubic yards. These materials show only 13% larger than 6" and 0% larger than 12".

We recommend modification of original report as follows:

1. Embankment design: Upstream slope = 3:1 outside; downstream slope = $2\frac{1}{2}:1$; center core $3/4:1$; with berms as originally proposed.
2. Placement of material represented by 62F1111 and 1114 adjacent to core section with + 6" material raked to outside shell. This material should be placed at not less than 125 p.c.f. dry density of the - 3" fraction. Four or five passes with D-7 or equivalent track type tractor should effect this density but it is suggested that a few density tests be made to assure this weight. Assuming an average of 40% larger than 3", the required density of the - 6" fraction would be about 137 p.c.f.
3. Coarser material placed in the outside shells could be specified as Class C fill.

Attachment

Prepared by:

Ray S. Decker

and


Lorn P. Dunnigan

cc: H. M. Kautz - Upper Darby, Pa.

RSD:LFD:vmo

MAXIMUM SECTION

STA 21+25



APPENDIX V
DESIGN REPORT

DESIGN REPORT

UPPER NORTH RIVER WATERSHED
SITE NO. 76
AUGUSTA COUNTY, VIRGINIA

This multiple-purpose structure is located in Augusta County, Virginia, approximately 15 miles north-northwest of Staunton. The transparent overlay (sheet 4 of this report) together with the Parnassus quadrangle published by the U.S. Geological Survey, may be used to locate the structure.

This dam is a class (c) structure (Engineering Memorandum SCS-27) and is designed in accordance with SCS criteria.

It is an earthfill structure having a cutoff trench to firm bedrock. The embankment materials are placed in a manner to afford foundation and embankment drainage through a rock toe drain.

The purpose of this dam is to reduce downstream flooding by providing temporary storage for the runoff from 17,370 acres of watershed. This temporary storage is released gradually through the principal spillway. This structure impounds 616 acre-feet of water for the city of Staunton which has its present water supply reservoir about a mile downstream from this dam. The 55-acre reservoir created by the permanent pool will afford limited recreational facilities which will be managed by the U.S. Forest Service.

The principal spillway consists of twin 42-inch diameter reinforced concrete water pipes. Discharge into the conduits is provided by a 9.0' x 10.5' reinforced concrete riser. There are three heavy duty gates attached to this riser for dewatering the reservoir and to permit utilization of the municipal water supplies.

There is a large emergency spillway cut through the right abutment. The 4.85 inches of floodwater storage below the crest of the emergency spillway, plus flow through principal spillway, will contain the maximum runoff produced by a storm in excess of 100-year frequency.

The inflow hydrographs used in the design of this structure were developed by the method described in Chapter 3.21 of Section 4, Hydrology, National Engineering Handbook.

The flood routing procedure used in the design is given in Section 5, Hydraulics, of the National Engineering Handbook.

The following table gives the results of the hydrologic and hydraulic determinations:

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
ENGINEERING & WATERSHED PLANNING UNIT
UPPER DARBY, PENNSYLVANIA

DRAWING NO.
VA-472-R

SHEET 1 OF 5

DATE 3/22/63

DESIGN REPORT

Factor Which Determines Stage	Surface Area Acres	Runoff in Inches	Peak Inflow c.f.s.	Peak Outflow c.f.s.	Elev. of Maximum Stage	Storage in Ac.-Ft.	Element of Structure Determined by Maximum Stage
50-year sediment accumulation	20 ¹	-	-	-	1978.0	168	Invert of riser dewatering gate
Water supply	55	-	-	-	2015.5	616	Crest of riser
100-year frequency storm moisture condition II	186	-	-	-	2060.5	5066	Below crest of emergency spillway
Greater than 100-yr. frequency storm moisture condition II ²	221	-	-	-	2070.0	7020	Crest of emergency spillway
1.0x9-hour point rainfall moisture condition II	227	7.65	15,659	6600	2074.7	8090	Design high water
2.50x9-hour point rainfall moisture condition II	274	24.17	46,370	45,000	2084.7 ³	10,500	Check top of dam

¹Borrow excavation in reservoir provides 248 acre-feet of storage.

²To reduce velocities in emergency spillway.

³Top of dam set at elevation 2084.00.

The time to empty the pool from the crest of the emergency spillway to the crest of the orifice is 6.10 days.

The geology report and Soil Mechanics Laboratory report were used to determine the adequacy of the design. Copies of these reports are attached.

The following publications were used in the design of this dam:

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
ENGINEERING & WATERSHED PLANNING UNIT
UPPER DARBY, PENNSYLVANIA

DRAWING NO.
VA-472-R

SHEET 2 OF 5

DATE 3/22/63


DESIGN REPORT

NE Handbook No. 5, Hydraulics
NE Handbook No. 4, Hydrology
NE Handbook No. 6, Structural Design
Technical Releases Nos. 2, 5 and 10

Copies of these publications may be obtained from Mr. Tom F. McGourin,
State Conservationist, USDA, Soil Conservation Service, Richmond, Virginia.

Concurred:

Gerald E. Oman
Design Engineer


R. C. Barnes, Jr.
State Conservation Engineer

Vincent McKeever
Hydrologist

Robert F. Fonner
Geologist

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
ENGINEERING & WATERSHED PLANNING UNIT
UPPER DARBY, PENNSYLVANIA

DRAWING NO.

VA-472-R

SHEET 3 OF 5

DESIGN REPORT

38°-20'



UPPER NORTH RIVER
SITE NO. 76

79°-15'

79°-10'

38°-15'

APPROVED:
JAMES H. DUNBAR, JR.,
ENGINEER, U.S. S. S.


U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
ENGINEERING & WATERSHED PLANNING UNIT
UPPER DARBY, PENNSYLVANIA

DRAWING NO.

SHEET 4 OF 5

DESIGN REPORT

Summary Sheet



Typical X-Section

I. Watershed data

A. Structure class	(c)	
B. Drainage area	17,370	Ac.
C. Time of concentration - T _c	8.6	Mins.
D. Hydrologic curve number - C _c		
1. Moisture condition II ⁿ	71	
2. Moisture condition III	88	

II. Principal spillway

A. Conduit		
1. Size (I.D.)	twin 42-	In.
2. Length	625.3	Ft.
B. Riser		
1. Size	10.5x9.0	Ft.
2. Height	39.0	Ft.
C. Weir length	21.0	Ft.
D. Orifice size	-	In.
E. Pond drain size	36	In.

III. Emergency spillway

A. Width	215	Ft.
B. Side slopes	variable 1.25 to 2.50	
C. Length of level section	40	Ft.
D. Exit slope	0.04	%
E. Maximum velocity at control section (D.H.W.)	9.4	Ft./Sec.
F. Duration of flow (D.H.W.) through emergency spillway	16.4	Mins.
G. Frequency of use	Less frequent than 100 year	

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
ENGINEERING & WATERSHED PLANNING UNIT
UPPER DARBY, PENNSYLVANIA

VA-472-R

SHE-1 5 5

DATE: 3/22/63

APPENDIX VI - REFERENCES

1. Recommended Guidelines for Safety Inspection of Dams, Department of Army, Office of the Chief of Engineers, 46 pp.
2. Design of Small Dams, U. S. Department of Interior, Bureau of Reclamation, 1974, 816 pp.
3. Geology of the Stokesville and Parnassus Quadrangles, Virginia, Reports of Investigations No. 19, E.K. Rader, Virginia Division of Mineral Resources, 1969, 30 pp.
4. Section 4, Hydrology, Part 1, Watershed Planning, SCS National Engineering Handbook, Soil Conservation Service, U. S. Department of Agriculture, 1964.
5. Hydrometeorological Report No. 33, U. S. Department of Commerce, Weather Bureau, U. S. Department of Army, Corps of Engineers, Washington, D. C., April 1956.
6. Technical Paper No. 40, U. S. Department of Commerce, Weather Bureau, Washington, D. C., May 1961.